PF REPORTER *Including Electronic Servicing*

10-YEAR CUMULATIVE SUBJECT INDEX 1951-1960

This index has been prepared to provide you with a ready reference to all PF REPORTER articles published to date.

Each item is indexed according to the *page on which the article begins*, together with the month and year of publication. Where there is more than one entry for a certain subject, the most recent coverage is usually shown first.

Where a *dash* precedes the entry, it refers to the key words (ahead of first comma) in the preceding entry. Example:

Selenium diodes, replaced with
germanium . . . . . 38, Mar 59
—trouble symptoms . . . . . 56, Sep 58

Major types of test equipment (oscilloscopes, CRT testers, etc.) and major components (capacitors, tubes, etc.) will generally be found in their own separate sections of the alphabetical listing. "Previews of New Sets" and "Video Speed Servicing" coverages are listed under "P" and "V" respectively. When looking for discussions about a specific TV trouble symptom, refer to the section of the TV receiver (tuner, sync, etc.) where this trouble is most likely to originate.

To help you further in finding the information you seek, you'll find listings of major feature articles for the past 10 years, categorized by subject, at the end of the main index section.

Copies of many back issues can be obtained at 50c each. Lists of available issues appear periodically in PF REPORTER.

AGC

See also
Keyed AGC

Amplified type in RCA Chassis KCS34B, checking performance . . . . . 16, Dec 57
Arvin Chassis TE-340 . . 37, Sep 54
Cathode follower, Arvin Chassis TE-341 . . . . 50, Feb 59
Excessive,
RCA Chassis KCS92D . . . . . 56, Sep 58
Figure of merit . . . . . 5, Jun 55
Intermittent high negative voltage, Stromberg-Carlson Chassis 622 . . . . . 60, Apr 60
Leakage from AGC line to B+ . . . . . 22, Apr 58
Negative picture . . . . . 30, Oct 60
—Emerson Model 1114J . . . . . 58, Nov 58
—Motorola Chassis TS-292C . . . . . 26, Jan 58
Overloading . . . . . 31, Jul 56
—Motorola Model 17T22 . . . . . 26, Jul 58
—with snow in picture . . . . . 50, May 59
Positive voltage on AGC line, RCA Chassis 5377 . . 60, Apr 60
Servicing guide by symptoms . . . . . 9, Mar 56
Step-by-step troubleshooting procedure . . . . . 24, Jul 60
Trouble, case history . . 27, Apr 57
—due to IF misalignment . . . . . 34, Sep 59
Variable delay, Olympic Model 21C28 . . . . . 35, Sep 52
6BU8, non-keyed . . . . . 29, Jun 56
—Zenith Chassis 15A25 . . . . . 18, Apr 58
—DuMont Chassis RA-400 . . . . . 16, Jun 58
—Zenith Chassis 17Z30 . . . . . 42, Jan 60

ALIGNMENT

AC-DC radio . . . . . 24, Dec 57
. . . . . 14, Mar 57
. . . . . 23, Mar 55
Accessories to save time . . . . . 50, Nov 56
. . . . . 37, Jan 52
Channel-frequency table for TV . . . . . 9, Sep 56
Checking test-equipment setup periodically . . . . . 46, Dec 58
Color TV circuits . . . . . 7, Jun 55
—chroma bandpass amplifier . . . . . 48, Jun 57
Communications receivers . . . . . 24, May 59
Continuous tuner, Raytheon TV Model M1611 . . . . . 44, Dec 58
FM radio . . . . . 16, Aug 57
Late-model TV sets . . . . 26, Jun 59
Sound IF and detector . . . . . 28, Mar 59
. . . . . 13, Jul 54
Test-equipment performance requirements . . . . . 11, Oct 54
Touch-up of sweep alignment . . . . . 9, Feb 54
Tracking superhet radios . . . . . 24, Dec 57
Transistor radios . . . . . 14, Aug 58
Tools and accessories . . 12, Mar 56
. . . . . 37, Jan 52
Tuning wand . . . . . 50, Nov 56
TV receivers, general . . 19, May 55
. . . . . 4, Jan 52
. . . . . 4, Nov 51
. . . . . 4, Jul 51
Tuners, TV . . . . . 28, Jul 59
. . . . . 60, Nov 57
. . . . . 11, Oct. 54
—response check . . . . 42, Mar 58
Video IF
—instructions . . . . . 30, Sep 60
. . . . . 22, Aug 60
. . . . . 18, Dec 58
. . . . . 16, Apr 58
—RCA Chassis KCS47B . . . . . 60, Dec 59
—stage-by-stage response check . . . . . 30, Sep 60
Video-sweep-modulated (VSM) method . . . . . 33, Sep 56

ANTENNAS

See also
Antenna rotators
Master-antenna systems

Attenuation of TV signals by rain, foliage, etc. . . . . 54, Dec 60
Base mounts for masts . 29, May 56
Basic characteristics . . . . 5, Sep 55
Basic principles of operation . . . . . 10, Feb 58
. . . . . 7, Apr 54
Basic types . . . . . 14, Aug 54
Broadband Yagi and conical . . . . . 12, Apr 58
Choosing most suitable type for situation . . . . . 26, Jul 60
Coaxial-cable lead-in . . 76, Nov 60
Codes prescribed for installations . . . . . 27, Nov 55
Color TV reception . . . 16, Nov 56
Directional response . . . 10, Feb 58
Drilling masonry in antenna-installation work . . . . 20, Jan 56
. . . . . 12, Dec 55
Formulas for dipole length . . . . . 11, Nov 54
Front-to-back ratio defined . . . . . 27, Dec 55
Ghosts not due to antenna . . . . . 56, Jun 60
Guying chart . . . . . 35, Jan 54
High-gain designs . . . . . 10, Mar 58
Holloway EXPO—*I.R.I.S.* . . . . . 15, Jan 56
Homeowner's TV Antenna Handbook . . . . . 39, Feb 59
Impedance matching . . . 10, Feb 58
Indoor types . . . . . 12, Mar 58
Installing properly . . . . 17, Mar 55
Insurance covering . . . 29, Feb 56
Lightning arrester . . . . 9, Feb 54
Limitations . . . . . 5, Sep 55
Line-cord types for TV . . . . . 60, May 60
Localizing defects in lead-ins . . . . . 15, Jul 54
Maintenance . . . . . 5, Jun 54
Matching transformers, 72- to 300-ohm . . . . . 76, Nov 60
Mountain-area installations to combat co-channel interference . . . . . 56, Sep 58
Polar graphs of response . . . . . 12, Jan 58
. . . . . 27, Dec 55
. . . . . 15, Jan 55
Recently-introduced designs . . . . . 8, Jul 58
. . . . . 12, May 58
Price lists of antennas and accessories . . . . . 39, Feb 59
Regulations governing installation . . . . . 27, Nov 55
Reradiating signal from mountain-top . . . . . 5, Nov 53
Resistor installation to allow measuring continuity . . . . . 25, Mar 52
Rhombic . . . . . 29, Feb 54
Shop system . . . . . 30, Jul 58
Signal attenuator . . . . . 21, Dec 54
Signal-distribution system sales . . . . . 58, Mar 60
Spring inspection for defects . . . . . 16, Apr 57
Switch for two antennas . . . . . 15, Mar 55
—for multiple antennas . . . . . 41, Jul 53
TACO *Topliner*, delay-line feature . . . . . 27, Aug 56
Terminal connections for twin-lead . . . . . 13, Dec 56
Tower maintenance . . . 14, Aug 56
Tower setup . . . . . 28, Sep 58
Troubleshooting . . . . . 54, Jul 56

ANTENNA ROTATORS

Alliance units . . . . . 27, Dec 54
CDR Models TR-2 and TR-4 . . . . . 27, Dec 54
Disassembly . . . . . 26, Jun 60
Long cable runs . . . . . 27, Mar 60
Servicing . . . . . 26, Jun 60

AUDIO, MISC.

See also
Audio amplifiers
Cartridges, phono
Commercial sound
Hi-fi consoles
Hi-fi systems
Hum
Intercoms

Microphones
Phonographs, special types
Record changers
Speakers
Speaker enclosures
Stereo
Test equipment
Turntables
Connecting cables . . . . 23, Aug 55
Custom installations—improving appearance . . . . . 25, Apr 55
Frequency-response adjuster, Blonder-Tongue *Audio Baton* . . . . . 26, Mar 59
High fidelity—its meaning . . . . . 31, Jan 54
Listening-room characteristics . . . . . 20, Oct 55
Magnetic wire and disc recorders . . . . . 13, Nov 54
Master control, Fisher Series 80-C . . . . . 20, Nov 55
Output-level indicators . . 23, Jul 55
Phono jack installation in AC-DC equipment . . . . . 25, Mar 52
Record care . . . . . 30, Dec 59 . . . . . 21, Sep 55
Tubes most widely used . . . . . 34, Jul 60
VU meters . . . . . 23, Jul 55

AUDIO AMPLIFIERS

Altec Lansing Model A-333-A . . . . . 41, May 52
Balancing push-pull output stages . . . . . 28, Jun 59
Cascode preamp for magnetic pickups . . . . . 31, Apr 55
Cathode-follower applications . . . . . 17, Aug 56
Distortion analysis . . . . 32, Apr 60 . . . . . 76, Feb 59
Equalization circuits . . . 30, Dec 59 . . . . . 26, Apr 59 . . . . . 20, Feb 58
Electro-Voice Model A-20C . . . . . 5, Dec 54
Fairchild 50-watt Model 260 . . . . . 27, Mar 55
Feedback circuits . . . . . 23, Jul 56
Juke-box amplifier fed by electronic organ . . . 60, Apr 60
Harmonic distortion . . . 32, Apr 60 . . . . . 76, Feb 59
Intermodulation distortion . . . . . 32, Apr 60 . . . . . 76, Feb 59 . . . . . 45, Jul 53
Kits by Triad . . . . . 11, Jan 55
Loudness controls . . . . . 30, Dec 59 . . . . . 45, Sep 53
Motorboating . . . . . 28, Jun 59
Music-power output . . . 48, Oct 60
National *Horizon 20, 10* and *5* . . . . . 27, May 55
Output-power ratings . . 48, Oct 60
Performance checking . . 17, Feb 55
Preamplifier
—Fisher Models PR-5, 50-PR-2 . . . . . 27, Jul 54
—construction project . . 24, Jun 55
—for use with Williamson amplifier . . . . . 37, Mar 52
Preamp-control unit
—McIntosh Model C108 . . . . . 17, Apr 54
—construction project . . 41, Jul 52
Record-compensation controls . . . . . 31, Jan 56
Small high-fidelity amplifier for construction project . . 19, Jul 53
Specifications and ratings defined . . . . . 19, Sep 52
Square-wave test for distortion . . . . . 32, Apr 60 . . . . . 27, May 51
Testing performance . . 37, Oct 56 . . . . . 25, Feb 55
Tone controls . . . . . 26, Apr 59
Tone-control circuits . . 30, Dec 59 . . . . . 26, Apr 59
Williamson type . . . . . 41, Jan 52
—modified version . . . . 15, Feb 54

AUDIO DETECTOR, TV

See
Sound detector, TV

AUTOMATIC TV TUNING

See
Tuners, TV—Motorized
Remote control, TV

AUTO RADIOS

See also
Hybrid auto radios
Signal-seeking auto radios
Battery polarity in cars . . . . . 70, Mar 58
Equipment needed for servicing . . . . . 38, Aug 60 . . . . . 25, May 57 . . . . . 37, Apr 54
FM, Lincoln Model 88BH . . . . . 40, Jul 58
Ford '57 models, service case histories . . . . . 42, Dec 60
Frequency drift, Mopar Model 848 . . . . . 42, Jan 60
Interference suppression, 1960 Saab car . . . . . 68, Sep 60
Power-transistor failure . . . . . 52, Nov 59
Rear-deck antenna installation . . . . . 18, Jun 57
Removal from 1955 Chevrolet . . . . . 22, Oct 57
Setting up service facilities . . . . . 38, Aug 60 . . . . . 37, Apr 54
Spark plates . . . . . 54, Jul 60
Transistorized, Motorola GV-800 . . . . . 38, Sep 58
Troubleshooting vibrator type . . . . . 11, Sep 55

BATTERIES

Current drain of small transistor radios . . . . . 52, Nov 59
Nickel-cadmium . . . . . 24, Apr 60
Rechargeable types recently developed . . . . . 24, Apr 60
Special types . . . . . 24, Apr 60 . . . . . 13, Jul 57
Storage and care . . . . . 24, Apr 60
Testing . . . . . 48, Sep 60 . . . . . 24, Apr 60
Transistor-radio types . . 13, Jul 57

BOOST

See also
Damper
Horizontal sweep
Capacitor . . . . . 28, May 60
Circuit design features . . . . . 33, Aug 56
Circuit-tracing . . . . . 60, Dec 59
Effect on vertical sweep . . . . . 39, Feb 57
Filter capacitor defective and causing jitter . . . . . 18, Aug 58
Lower than normal, Admiral Chassis 19T1 . . . . . 82, May 60
Theory of operation . . . 33, Aug 56

BUSINESS

Advance planning to save time . . . . . 19, Aug 56
Antenna insurance . . . . 29, Feb 56
Antenna sales . . . . . 50, May 58
Auto-radio service specialty shop . . . . . 38, Aug 60
Bank loans for service business . . . . . 76, Jun 57
Charging for "dog" service job . . . . . 16, Aug 58
Check list for customer to use before calling for service . . . . . 23, Jun 58
Christmas gift promotions for service shop . . . . . 42, Nov 59
Christmas-season advertising ideas . . . . . 46, Nov 60
Clothing suitable for service calls . . . . . 16, Aug 58
Collecting bills for service work . . . . . 20, Jun 60 . . . . . 62, May 59 . . . . . 38, Dec 57 . . . . . 35, Mar 57
Color TV, sales and service methods . . . . . 21, Dec 56
—home demonstrations . . . . . 18, Feb 58
Contracts for TV service . . . . . 34, May 60
Cost accounting for shop . . . . . 86, Nov 56
Customers' reaction to quality of service . . . . . 34, Dec 60 . . . . . 56, Aug 59
Customer service records . . . . . 40, Apr 60
Dealing with people . . . 28, Jun 58 . . . . . 13, Oct 54
Direct-mail advertising . . . . . 40, Feb 60 . . . . . 42, Sep 59
—prepared by specialist . . . . . 38, Sep 60
Efficiency improvements in shop . . . . . 40, Apr 60
Estimating labor charge . . . . . 54, Sep 60 . . . . . 13, Apr 54
Estimating repair costs from simple in-home tests . 81, Oct 57
Estimating shop-service charges . . . . . 34, Sep 58
Evening calls . . . . . 12, Jun 58
Fall sales campaign . . . 38, Sep 60
Field report on Television Maintenance Co., Canton, Ohio . . . . . 16, Jul 57
Fixer fees for specific repairs . . . . . 34, Jan 59
Free tube testing by service shops . . . . . 44, Jul 59
Future of radio-TV service industry . . . . . 58, Mar 59
Guarantees on service work . . . . . 50, Apr 58
"Hams," relations with servicemen . . . . . 42, Nov 59
Hiring and keeping qualified technicians . . . . . 64, Jan 57 . . . . . 15, Jun 57
Income-tax payments on service-contract receipts . . . . 56, Aug 59
Income-tax returns . . . . 44, Mar 60
Insurance for service shops . . . . . 21, Jan 52 . . . . . 4, Mar 51
Inventory control for shop . . . . . 34, Dec 60 . . . . . 36, Mar 60
Itemized bill for complete TV overhaul . . . . . 22, Feb 58
Life expectancy of TV sets . . . . . 44, Jun 59
Loyalty of customers . . 44, Jul 59
Mailing list, keeping up to date . . . . . 34, May 60
Names of service shops . . . . . 42, Oct 58 . . . . . 16, Jul 58
New-set sales by service dealer . . . . . 30, Aug 60 . . . . . 42, Nov 59
Objectives or goals of business enterprise . . . . . 34, May 60
Old TV sets—overhaul or patch up? . . . . . 40, Feb 60
Paper bags for handing spare parts to customers . . 40, Apr 59
PEET program . . . . . 30, Aug 60
Phone-answering device . . . . . 15, Dec 55
—service . . . . . 40, Apr 60
Phone calls for service, taken by nontechnical person . . 56, Nov 58
Phonograph-sales statistics . . . . . 56, Nov 58
Planning in advance to save time . . . . . 58, Mar 59
Premiums to customers . . . . . 20, Apr 58
Presenting service bill to customer . . . . . 56, Nov 58
Pricing guide for TV service work . . . . . 54, Sep 60
Productive work during short time intervals . . . . . 44, Jun 59
Promoting minor repairs . . . . . 40, Apr 59
Production changes, explaining to customer . . . . . 12, Jun 58
Publicity for shop . . . . 60, Aug 57
Rentals of TV sets . . . 28, Jan 58
Renting a shop . . . . . 50, May 58
Repeat business . . . . . 44, Jul 59 . . . . . 86, Mar 57
Routine chores, best time to do . . . . . 68, Feb 59
Routing service calls . . 17, Sep 55
Rush periods, easing strain . . . . . 52, Oct 60
Sales displays for accessories in service shop . . . . . 18, Jun 58
Saving time, on bench jobs . . . . . 34, Nov 58 . . . . . 5, May 52
—on servicing "dogs" . . 38, Feb 58
Scheduling service calls to be on time . . . . . 56, Aug 59
Schools for technical training . . . . . 17, Oct 56 . . . . . 13, Sep 56
Selling antenna service . 16, Apr 57
Selling multiple-outlet antenna systems . . . . . 58, Mar 60
"Service clubs" . . . . . 40, Apr 60
Service shop converted from outmoded gas station . . . . . 58, Mar 59
"Service specials" during slack periods . . . . . 16, Jul 58
Shop tickets . . . . . 25, Jan 55
"Soft-sell" approach to accessory sales . . . . . 52, Oct 60 . . . . . 42, Sep 59
Summer sales-promotion ideas . . . . . 30, Jun 60
Summer slump remedies . . . . . 17, Jul 56
Truck, buying for shop . . . . . 50, Dec 57
"Upgrading" courses to increase technical know-how . 17, Oct 56
Weekly work record . . 15, Jun 56
Welcome Wagon . . . . . 40, Apr 59
"While-U-Wait" repair bench . . . . . 60, Jul 58
Window displays for shop . . . . . 25, Jun 56
"Winter changeover" list . . . . . 60, Dec 59
"Worry breaks" to ease tension . . . . . 40, Dec 59

CABINET WORK

Built-in TV, providing for ventilation . . . . . 48, Jan 60 . . . . . 50, Dec 57
Casters added to TV cabinet . . . . . 19, Jul 55
Grille-cloth installation . . . . . 34, Sep 59
Hinged control-panel door, replacement . . . . . 30, Sep 56
Plastic covering to modernize old TV cabinet . . . . 14, Jan 57
Rattle repaired by gluing loose joint . . . . . 32, Dec 59
Shop-cabinet construction . . . . . 24, Nov 55

Touch-up . . . . . 24, Sep 56
—while chassis is in shop for repairs . . . . . 50, May 58

CAPACITORS
Also see
Electrolytic capacitors
Bypass function defined . . . . . 68, Sep 60 . . . . . 17, Oct 56
Ceramic types . . . . . 16, Sep 56 . . . . . 7, Jul 51
Checking with VTVM voltage function . . . . . 19, Jul 55
Close-tolerance types—applications . . . . . 27, Jul 52
Color codes . . . . . 14, Oct 57
Decoupling function defined . . . . . 68, Sep 60
Leakage check with VTVM . . . . . 30, Jul 58
Molded tubular . . . . . 16, Sep 56
Negative temperature coefficient . . . . . 48, Dec 59 . . . . . 32, Apr 59
Printed-wiring board mounting . . . . . 19, Feb 56
RC coupling—point of theory . . . . . 58, Nov 58
Stock of most popular types . . . . . 29, May 57
Temperature-compensating . . . . . 48, Dec 59 . . . . . 32, Apr 59
Types, characteristics, applications . . . . . 9, Jan 56 . . . . . 5, Jan 55
"Whiskers" on ceramic disc unit . . . . . 74, Aug 59

CAPACITOR TESTERS
Aerovox Model 97 . . . 60, Sep 58
Arkay Model CA-40 . . 36, Dec 60
Bridge-type—basic theory . . . . . 19, Mar 55
Century Model CT-1 . . 38, Nov 57
Electrolytic leakage test . . . . . 19, Mar 55
Jackson Model 591 . . . 68, Sep 59
PACO Model C-25, in-circuit type . . . . . 60, Nov. 60
Pyramid Model CRA-2 . . . . . 40, Jun 58
—Model CRA-1 . . . . . 21, Apr 55
Simpson Model 383A in-circuit leakage tester . . . . . 23, Sep 56
—Model 383 . . . . . 10, Dec 55
Sprague *KWIK-TEST* Model KT-1 . . . . . 27, Nov 54
Sprague Model TO-5 *Tel-Ohmike* . . . . . 42, Mar 58
—Model TO-4 . . . . . 15, Jul 54

CARTRIDGES, PHONO
Ceramic high-quality types . . . . . 26, May 56
Crystal type . . . . . 5, Nov 51
Frequency-response checks . . . . . 53, Nov 52
Replacement hints . . . 38, Jun 58
Stereo, earliest types . . 10, Jul 58
Stylus-wear checking . . 32, May 58

CHASSIS DESIGN, TV
Admiral 10" Chassis 14YP3B . . . . . 14, Dec 56
Captive tube shields . . . . . 29, Jun 56
CBS Model 3T615 . . . . 17, Jan 56
Crosley "Super V" Chassis 426 . . . . . 21, Jun 54
Dip-soldered terminals in General Electric TV and radios . . . . . 33, May 53
Emerson 8" *Port-O-Rama* Model 1232 . . . . . 19, Feb 57
General Electric *Designer* series, Chassis M4 . . . . . 40, Jul 58
General Electric 9" Model 9T001 . . . . . 27, Mar 57
General Electric Model 14T007 . . . . . 9, Oct 55
Hot chassis, isolation from cabinet . . . . . 54, Jun 59 . . . . . 44, Mar 59
—shock protection . . . 18, Mar 57
Motorola Chassis TS- 552 . . . . . 26, Jun 59
Philco *Predicta* Chassis 9L37 . . . . . 28, Apr 59
RCA 8" Chassis KCS100B . . . . . 21, Aug 56
Solderless wire-wrap terminals . . . . . 15, Oct 55
Sylvania *dualette*, Chassis 1-543-1 . . . . . 48, Aug 59
Sylvania Chassis 1-513-1 . . . . . 23, Apr 54
Tube layout in TV sets . . . . . 4, Sep 51
Vertical, with front-mounted controls . . . . . 25, May 56
1961 TV models . . . . . 32, Nov 60

CIRCUIT DESIGN, TV
See also
under appropriate
sections of TV set
(video IF, vertical sweep, etc.)
Admiral Chassis 18XP4BZ . . . . . 27, Feb 55
Admiral Chassis 20A2 . 17, Aug. 54
Arvin Chassis TE-331 . . 35, Sep 52
Caltech Chassis T1 . . . . 19, Jan 55
Crosley "Super V" Chassis 426 . . . . . 21, Jun 54
Emerson Chassis 120205B . . . . . 25, Nov 54
General Electric Model 21C240 . . . . . 37, Sep 54
General Electric Model 21T1 . . . . . 33, May 53
General Electric Model 24C101 . . . . . 31, Mar 52
Interacting circuits in different sections of receiver . . . . . 26, Feb 58
Magnavox Chassis CT-331 . . . . . 37, May 52
Motorola Chassis WTS-518Y . . . . . 25, Oct 54
Motorola Chassis TS-325 . . . . . 37, May 52
Muntz Chassis 47A4 . . 21, Mar 55
Olympic Chassis AD . . . 19, Jun 55
Philco RF Chassis 71, Sweep Chassis G1 . . . . . 37, Jul 52
Popularity of various types . . . . . 28, May 59 . . . . . 18, Dec 57
Radio Craftsman Model RC201 . . . . . 23, Nov 51
RCA Chassis KCS66 . . 25, Jan 52
RCA Chassis KCS84 . . 27, May 54
Sylvania 110° Chassis 1-537 . . . . . 19, Apr 57
Sylvania Chassis 1-521-2 . . . . . 15, Dec 54
Sylvania Chassis 1-260 . . . . . 25, Jan 52
Westinghouse Chassis V-2342 . . . . . 9, Dec 55
Westinghouse Chassis V-2260-12 and -14 . . . . . 11, Jul 54
Zenith Chassis 21K20 . . . . . 51, Nov 52
Zenith Chassis 20J21 . . . . . 31, Mar 52
1961 models . . . . . 32, Nov 60

CIRCUIT THEORY
AFC in FM radios . . . . 25, July 56
Amplifiers, Class A . . 58, Nov 59
Oscillators, theory of operation . . . . . 60, Feb 60
Resonant circuits . . . . . 23, Apr 57 . . . . . 25, Mar 57 . . . . . 25, Feb 57
Time constants of RC circuits . . . . . 27, Mar 56

CITIZENS BAND
Antenna types . . . . . 82, May 60
FCC field-office addresses . . . . . 36, Feb 60
Licensing information . . 36, Feb 60
Mobile-installation hints . . . . . 70, May 60
Range of Class D units 36, Feb 60
Receiver circuits, typical . . . . . 70, May 60
Rules for operation . . . . 36, Feb 60
Specifications of various transceivers . . . . . 36, Feb 60
Test unit for transceivers, Seco Model 500 . . . . . 62, Oct 60
Transmitter circuits, typical . . . . . 70, May 60

COLOR TV
Aligning demodulator . . 25, Sep 57
Aligning receiver . . . . . 7, Jun 55
Answers to customers' questions . . . . . 21, Jul 55
Antenna requirements . . 16, Nov 56
Bandpass-amplifier alignment . . . . . 48, Jun 57
Bar patterns . . . . . 7, Aug 54
Black-and-white reception on color set . . . . . 19, Jan 54
Block diagram of chroma section in recent models . . . . . 52, Oct 59
Burst signal . . . . . 10, Jan 54
CBS field-sequential system . . . . . 5, Jul 51 . . . . . 15, Sep 51
Chrominance circuits . . . . . 7, Nov 54
Chrominance signal . . . . 7, Aug 54
Circuits common to black-and-white sets . . . . . 7, Oct 54 . . . . . 7, Sep 54
Colorimetry . . . . . 9, Jun 54
Color-killer service hints . . . . . 36, Dec 59 . . . . . 28, Jan 57
Color-sync troubleshooting . . . . . 36, Jul 60 . . . . . 28, May 58
Convergence components . . . . . 7, Mar 55
—RCA Chassis CTC7 . . . . . 22, May 58
—using dot generator . . . . . 13, Jun 54
Crosshatch generator to check chroma phase . . . . . 44, Sep 59
"Crystal-ringing" color-oscillator control . . . . . 36, Dec 59
DC restoration for signals . . . . . 19, Aug 54
Degaussing coil . . . . . 21, Apr 56
Delay line . . . . . 25, Sep 54 . . . . . 17, Jul 54
Demodulating color signals . . . . . 7, Dec 54 . . . . . 14, Jan 54
Demodulator circuits . . . 7, Jan 55
Differences from monochrome . . . . . 5, Jan 54
Dynamic-convergence control failures, RCA Chassis CTC5A . . . . . 28, Dec 58
Field report on sales and service . . . . . 21, Dec 56
Focus-circuit changes in RCA sets . . . . . 26, Mar 58
Focus control, RCA Chassis CTC7 . . . . . 50, Jul 59
Glossary of terms . . . . . 87, Jan 54
High-level demodulation . . . . . 21, Dec 55
High-voltage interlock . . . . . 14, Dec 56
Home demonstrations . . 18, Feb 58
I and Q signals . . . . . 7, Jul 54
Installing receiver . . . . . 19, Feb 55
Isolating trouble . . . . . 52, Oct 59 . . . . . 28, Jul 57
Loss of color, case histories . . . . . 28, Nov 57
Luminance section . . . . . 7, Oct 54
Luminance signal . . . . . 7, Aug 54
Magnetic-convergence CRT . . . . . 7, Mar 55
Matrixing color signals . 19, Aug 54 . . . . . 14, Jan 54
—circuit details . . . . . 7, Jan 55
Motorola TS-905, dynamic-convergence circuits . . . . . 12, Nov 56
NTSC signal . . . . . 5, Mar 54 . . . . . 23, Nov 53
NTSC system standards . . 9, Sep 53 . . . . . 5, Jul 53
Phase diagram of color signal . . . . . 5, May 54
Philco Chassis TV-123, filament-fuse failure . . . . . 54, Dec 60
Picture tube . . . . . 7, Feb 55 . . . . . 6, Jan 54
Picture-tube circuits . . . . 7, Feb 55
Poor reception on Channel 14 . . . . . 60, May 58
Post-acceleration CRT . . . . . 25, Jan 56
Quadrature transformer . . . . . 23, Jan 56
RCA CTC5 series . . . . 12, Nov 56
Rainbow generator "sidelock" in color sync . . . . . 14, Aug 57
Service case histories . . . . . 56, Jun 57 . . . . . 17, May 55 . . . . . 19, Apr 55 . . . . . 19, Feb 55
Servicing guide by symptoms . . . . . 30, Feb 60
Service short cuts . . . . . 30, Feb 57
Setup adjustments for receiver —magnetic convergence . . . . . 7, May 55
—electrostatic convergence . . . . . 7, Apr 55
Signal-substitution testing . . . . . 25, Sep 57
Sweep components . . . . 19, Mar 54
Synchronizing color signals . . . . . 10, Jan 54
Test-equipment requirements . . . . . 15, Feb 56 . . . . . 11, Feb 54
Troubleshooting receivers . . . . . 52, Oct 59 . . . . . 7, Sep 55 . . . . . 7, Aug 55 . . . . . 7, Jul 55
Vector analysis of color-signal phase . . . . . 7, Aug 54 . . . . . 17, Jul 54
Video sweep analysis . . . 25, Jul 55 . . . . . 13, May 55
Video-sweep-modulated (VSM) alignment . . . . . 33, Sep 56
Westinghouse 22" 1957 model . . . . . 44, May 57
3.58-mc oscillator service hints . . . . . 38, Dec 59

COLORBLOCK REFERENCE CHARTS
I/Q color circuits and transmission standards . . . . . June 54
R-Y/B-Y color circuits . . . Aug 54
I/Q color circuits with matrix-circuit variations . . . . . Oct 54
Vector diagram of color-signal phase . . . . . Dec 54
Transmitted color stripe . . . Feb 55
Hickok Model 655XC color-bar generator . . . . . Apr 55
Jackson Model 700 and 712 color-bar generators . . . . . Jun 55
Triplett Model 3439 color-bar generator . . . . . Aug 55
RCA Model WR-61A color-bar generator . . . . . Oct 55
Win-Tronix Model 150 rainbow generator . . . . . Dec 55
Formation of composite color signal . . . . . Feb 56

Installing 21AXP22 color picture tube . . . . . Apr 56

COLOR-BAR GENERATORS
Hickok Model 660 27, Nov 56
Hickok Model 655XC . 27, Nov 54
. . . . . 19, Sep 54
Hycon Model 616 . . . . 48, Nov 58
Jackson Model 712 . . . . 17, Dec 54
Precision Apparatus Model E-420
. . . . . 16, Jan 57
RCA Model WR-61A . 11, Aug 54
Simpson Model 430 . . . . 40, Jun 58
Triplett Model 3439 . . . . 25, Jul 55
Win-Tronix Model 250 30, Jan 58

COMMERCIAL SOUND
Acoustic problems in gymnasium
. . . . . 28, Jun 60
. . . . . 44, Mar 59
Choosing correct PA amplifier for a given job . . . . . 36, Nov 59
Constant-voltage hook-up for speakers . . . . . 16, Dec 57
Filters for amplifier output
. . . . . 52, Jan 59
Football-stadium PA installation
. . . . . 28, Jun 60
Impedance matching of speakers to amplifiers . . . . . 52, Jan 59
Microphone phasing . . . . 52, Jan 59
PA amplifier specifications
. . . . . 36, Nov 59
PA amplifier-speaker interconnections . . . . . 19, May 57
PA speaker location for best results
. . . . . 28, Jun 60
PA-system installation hints
. . . . . 24, Nov 58
Speakers for PA systems
. . . . . 38, Mar 57
Speaker connections . . . . 52, Jan 59
Typical rack-mounted installation in business building . . 21, Jan 57

COMMUNICATIONS RADIO
See also
Citizens band
Installing in automobile . 26, Jan 59
Power supplies, converter and inverter . . . . . 34, Feb 59
Receiver, alignment and calibration
. . . . . 24, May 59
—circuit features . . . . . 24, Mar 59
—controls defined . . . . 24, Mar 59
—servicing hints . . . . . 24, Mar 59
Single-sideband adapters for receivers . . . . . 38, Oct 60
Special receiver features
. . . . . 17, Nov 54

CONTROLS
Brightness maximum and uncontrollable Hallicrafters Chassis A1400D . . . . . 60, Dec 59
Cleaning with solvent injector
. . . . . 15, Dec 55
Contrast . . . . . 26, Oct 59
. . . . . 7, Mar 52
Focus-control burnout, Olympic Model 752 48, Feb 60
Height and vertical linearity, repeated burnout in Crosley Chassis 385 . . . . . 44, Mar 59
Printed-wiring board mounting
. . . . . 19, Feb 56
Replacement techniques 34, Oct 60
. . . . . 15, May 55
Resetting after tube replacement
. . . . . 26, Apr 60
Shaft cutting . . . . . 50, Jul 59

CONVERSION TO LARGER PICTURE-TUBE SIZE
Deflection-angle increase causes problems . . . . . 72, Mar 60
Motorola VF103 to 14" 15, Jul 51
Olympic XL210 to 20" 21, Oct 51
RCA Model 730TV1 to 14"
. . . . . 11, May 51
RCA Chassis KCS47C, 17" to 21"
. . . . . 60, Apr 60
630-type chassis to 16" or 17"
. . . . . 5, Mar 51

CRT TESTERS
Authorized Model 101F 19, Sep 55
Authorized Mfrs. Service type
. . . . . 11, Feb 55
B & K Model 440 . . . . 64, Mar 60
B & K Model 350 . . . . 24, Oct 55
Mercury Model 300 *Combination Tester* . . . . . 36, Dec 60
Precision Series CR-30
. . . . . 30, Nov 55
Raytronic Cathode Beamer
. . . . . 11, Feb 55
—gas test . . . . . 19, Sep 55
Substitution unit for CRT and yoke, Tele-Check Model CR-99
. . . . . 23, Sep 56
Vis-U-All Model 200 48, Dec 58
Vitameter . . . . . 28, Jul 56

COILS
See
Transformers and coils

CRYSTAL DIODES
See
Germanium diodes

DAMPER
Recently-introduced types
. . . . . 30, Jun 59
Repeated failure, Motorola Chassis MTS-537 . . . 30, Jan 59
Resistance reading to ground, General Electric Chassis MM
. . . . . 70, Oct 60
Short from isolated filament circuit to ground . . . 54, Dec 60
Theory of operation 32, Feb 59
. . . . . 33, Aug 56
Tube failure . . . . . 30, May 57
Types for 110° sweep . 30, Jun 59

DC RESTORERS
Servicing guide by symptoms
. . . . . 17, Nov 55
Theory of operation . . . 10, Aug 56
. . . . . 7, May 52

DECIBELS
Formulas and applications
. . . . . 66, Aug 59
. . . . . 28, Jul 56
. . . . . 41, Mar 52
Sample problems for figuring
. . . . . 5, May 53

DOT GENERATORS
Admiral portable Model TE-100
. . . . . 30, Aug 57
Hickok Model 600 . . . 27, Nov 56
Hickok Model 650C Videometer
. . . . . 13, Jun 54
Hycon Model 616 . . . . 48, Nov 58
Jackson Model 712 . . . 17, Dec 54
Precision Apparatus Model E-420
. . . . . 16, Jan 57
RCA Model WR-36A . 11, Aug 54
Simpson Model 434 . . 20, Mar 56
Triplett Model 3438 . . . 10, Feb 56
Unstable pattern, using line sync with RCA WR-36A generator
. . . . . 18, Aug 58
Win-Tronix Model 250 . 30, Jan 58
Win-Tronix Model 160 . 24, Oct 55

ELECTROLYTIC CAPACITORS
Checking performance . . 22, Oct 58
Low-voltage type, testing
. . . . . 44, Mar 59
Meter pegs during test
. . . . . 68, Sep 60
Miniature type . . . . . 16, Sep 56
Power factor . . . . . 23, Nov 55
Testing for leakage between sections . . . . . 56, Sep 58
Twist-prong type, replacement
. . . . . 14, Feb 57
TV applications . . . . . 22, Oct 58

FIELD-STRENGTH METERS
Applications . . . . . 32, Nov 59
. . . . . 4, Mar 51
Blonder-Tongue Model FSM-1
. . . . . 52, May 58
Jerrold Model TMT, transistorized portable . . . . . 70, Oct 59
Jerrold Model 704B . . 30, Aug 57
Meaning of "microvolts per meter"
. . . . . 31, Feb 54
Shell Model FS-3 . . . . . 46, Aug 60
Simpson Model 498-A . 48, Dec 58
Specifications of various types
. . . . . 32, Nov 59

FLYBACK TRANSFORMERS
See
Horizontal output transformers

FLYBACK TESTERS
B & K Model 1070 *Dyna-Sweep*
. . . . . 68, Feb 60
B & M Model 50-A *Inductive Winding Tester* . . . . . 36, Jul 57
Doss *Pioneer 250* . . . . 68, Nov 59
EICO Model 944 . . . . . 30, Apr 58
. . . . . 15, Jun 55
Radio City Products Model 123 *Flybacker* . . . . . 15, Jun 55
. . . . . 13, Jun 54
Seco Model FB-4 . . . . . 15, Jun 55
Sencore Model SS-105 . . 60, Jan 60
Win-Tronix Model 820 *Dynamic Sweep Circuit Analyzer*
. . . . . 10, Feb 56
Win-Tronix Model 810 . 30, Nov 55

FM RADIOS
See
Tuners, FM and AM-FM

FRINGE-AREA TV INSTALLATIONS
Cascode tuner installation to boost gain . . . . . 17, Jan 54
Increasing tuner sensitivity
. . . . . 5, Sep 54
"Peaking" receiver performance
. . . . . 9, Jan 54
Valley location far from stations
. . . . . 44, Dec 58

FUSES
See also
Fusible resistors
Applications . . . . . 5, Jul 54
Characteristics of different types
. . . . . 21, Jun 57
Chemical type in recent RCA sets
. . . . . 56, Nov 59
Circuit-breaker trouble
. . . . . 82, May 60
Filament fuse wire blows, Philco color TV Chassis TV-123
. . . . . 54, Dec 60
Frequent burnout . . . . . 60, Apr 60
Other protective devices
. . . . . 30, Apr 60
Specification charts
. . . . . 15, May 52
Stock of most popular types
. . . . . 29, May 57
Sweep-circuit fuse blows, RCA Chassis KCS107D . . . 68, Sep 60

FUSIBLE RESISTORS
Cross-reference of part numbers and values . . . . . 28, Dec 58
Miscellaneous information
. . . . . 70, Oct 60
. . . . . 30, Apr 60
Operating characteristics
. . . . . 22, Jan 58

GARAGE-DOOR OPENERS
Alliance unit installation
. . . . . 12, Jul 58
Perma-Power unit installation
. . . . . 12, Jul 58
Perma-Power Model RC101
. . . . . 27, Jan 55

GERMANIUM DIODES
Characteristics and applications
. . . . . 23, May 57
Determining polarity . . . 42, Jun 60
Power rectifiers, General Electric types . . . . . 32, Sep 57
Substituted for selenium diodes in horizontal AFC . . . . 38, Mar 59

HARMONIC DISTORTION
See
Audio amplifiers—distortion

HI-FI
See
Audio, misc.
Audio amplifiers
Cartridges, phono
Hi-fi consoles
Hi-fi systems
Hum
Record changers
Speakers
Speaker enclosures
Stereo
Turntables

HI-FI CONSOLES
Capehart Model RP-154
. . . . . 33, Sep 54
Columbia Model 583 . . 20, Feb 58
Vibration of cabinet at high volume levels . . . . . 76, Nov 60

HI-FI SYSTEMS
Cabinet for custom system
. . . . . 29, Mar 54
Checking performance . . 23, Feb 54
Diagnosing trouble . . . . 34, Oct 58
Distortion measurements
. . . . . 32, Apr 60
. . . . . 76, Feb 59
Equipment required for servicing
. . . . . 34, Oct 58
Localizing trouble on home call
. . . . . 34, Feb 60
. . . . . 24, Dec 58
Music as aid to troubleshooting
. . . . . 50, Aug 60
Popping noise when record changer shuts self off . . . . . 60, Apr 59
Restoring good performance
. . . . . 29, Nov 54
Symptom analysis . . . . . 34, Feb 60
. . . . . 24, Dec 58
Tube types most often employed
. . . . . 34, Oct 58
TV sound fed in . . . . . 76, Sep 59
. . . . . 30, Jan 59

HIGH VOLTAGE
See also
Damper
Horizontal sweep
Picture tubes
Arcing internally in capacitors
. . . . . 41, Sep 53
. . . . . 70, Oct 58
Arc tests in troubleshooting
. . . . . 29, Oct 56
Auxiliary supply for bench
. . . . . 29, Sep 52
Absent or low . . . . . 34, Mar 60
—Admiral Chassis 15C1
. . . . . 60, Dec 59
—due to defective drive component at output-tube grid
. . . . . 44, Dec 58
—due to disabled horizontal oscillator . . . . . 82, May 60
. . . . . 56, Sep 58
—due to insulation breakdown in oscillator circuit, DuMont Chassis RA-400 70, Oct 58
Blooming of raster . . . . 48, Feb 60
Effect of disconnecting yoke
. . . . . 22, Apr 58
Doubler circuit, capacitor failure
. . . . . 29, Jan 56
—trouble in Sylvania Model 23M1 . . . . . 56, Jun 60
Gradual weakening, General Electric Model 17C125
. . . . . 82, May 60
Intermittent loss due to open 6CD6 heater, DuMont Model RA-162

52, Nov 59
Lead protected on bench by rubber ball . . . . . 25, Mar 52
Low enough to kill raster . . . . . 44, Mar 59
Low when bad CRT is connected . . . . . 72, Mar 60
Normal, but no raster visible . . . . . 26, May 60
Restored by removing horizontal AFC diode . . . . . 82, May 60
Servicing components in HV cage . . . . . 15, May 57
Servicing guide by symptoms . . . . . 14, Sep 57
Stabilizing system in General Electric Model 21T7 . . . . . 39, Nov 53
Troubleshooting . . . . . 17, May 55

HORIZONTAL AFC

See also
Horizontal oscillator
Horizontal sync
Blanking bar in center of screen due to wrong diode connections . . . . . 72, Mar 60
Dual-diode phase detector for multivibrator . . . . . 22, May 54
—troubleshooting . . 21, Dec 54
Feedback resistor burned, Mirrortone Chassis 9034A . . . . . 60, Apr 59
Gruen circuit . . . . . 36, Jul 59
. . . . . 31, Sep 54
Pulse-width type, adjustment on home call . . . . . 29, Jun 57
—isolating cause of pulling . . . . . 24, Apr 58
—RCA Chassis KCS122 . . . . . 34, Nov 59
—theory . . . . . 15, Jun 54
—troubleshooting . . . . 36, Jul 58
. . . . . 15, Nov 54
Reactance tube and dual-diode phase detector . . . . 31, Sep 54
. . . . . 23, Aug 54
—recent Motorola design . . . . . 28, Jul 60
—recent Zenith design . . . . . 36, Jul 59
Selenium diodes, replaced with germanium . . . . . 38, Mar 59
—trouble symptoms . . 56, Sep 58
Servicing guide by symptoms . . . . . 50, Mar 57
Step-by-step troubleshooting procedure . . . . . 40, May 60
Triode-type phase detector . . . . . 23, Sep 55
Troubleshooting hints . . . . . 7, Mar 53

HORIZONTAL OSCILLATOR

See also
Horizontal AFC
Horizontal sweep
Drift in frequency . . . . . 38, Dec 56
—Bendix Model C174-2 . . . . . 82, May 60
Far off frequency, Admiral Chassis 19T2 . . . . . 70, Oct 58
Grid voltage, normal, on first section of multivibrator . . . . . 50, Feb 59
Gruen circuit . . . . . 36, Jul 59
. . . . . 31, Sep 54
Inoperative, resulting in no raster . . . . . 82, May 60
. . . . . 70, Oct 58
. . . . . 56, Sep 58
Multivibrator, individual component functions . . . . . 62, Oct 58
—service hints . . . . . 62, Aug 59
—theory of operation . 22, May 54
—troubleshooting check chart . . . . . 62, Oct 58
Ringing-coil, checking . 33, May 52
—defective . . . . . 23, Feb 56
Servicing guide by symptoms . . . . . 50, Mar 57
Sine-wave type . . . . . 31, Sep 54
. . . . . 23, Aug 54
—recent Motorola design . . . . . 28, Jul 60
—recent Zenith design . . . . . 36, Jul 59
Synchroguide theory . . 15, Jun 54
—modernized circuit in RCA Chassis KCS122 . . 34, Nov 59
Three pictures side by side . . . . . 56, Sep 58
Two pictures side by side . . . . . 13, Dec 56

HORIZONTAL OUTPUT TRANSFORMERS

Checking resonant frequency . . . . . 27, Apr 55
. . . . . 21, Nov 51
Design features . . . . . 15, Nov 55
Frequent burnout . . . . 76, Sep 59
Overheating, locating cause . . . . . 60, May 58
Replacement considerations . . . . . 52, May 57
Replacement procedure . . . . . 32, Feb 60
. . . . . 11, Jul 53
. . . . . 15, Sep 53
Theory of operation . . 26, Apr 56

HORIZONTAL SWEEP

See also
Boost
Damper
High voltage
Horizontal oscillator
Horizontal output transformers
Yokes
Arcing in flyback-circuit capacitor . . . . . 70, Oct 58
Barkhausen oscillations . . . . . 15, Nov 51
Component-function explanation . . . . . 28, May 60
Critical circuit components . . . . . 9, Nov 55
Direct-drive circuit, RCA Chassis KCS47 . . . . 56, Nov 60
—RCA Chassis KCS68 . . . . . 62, Aug 59
Drive line, DuMont Chassis RA-340 . . . . . 18, Aug 58
—Motorola Model 21T4AC . . . . . 60, Apr 60
Drive voltage, effect on tube life . . . . . 39, Feb 57
Flyback-system operating theory . . . . . 26, Apr 56
Foldover . . . . . 31, Jul 52
Grid capacitor of output tube causing loss of high voltage . . . . . 44, Dec 58
Grid circuit of output stage . . . . . 28, May 60
Keystone effect, not due to yoke . . . . . 15, Oct 55
—with "pleats" in raster . . . . . 76, Sep 59
Linearity adjustment in home . . . . . 15, Oct 55
Nonlinearity . . . . . 34, Mar 60
. . . . . 5, May 52
Notches in sides of raster due to power-supply fault . . 52, Feb 59
Output tube
—drive insufficient . . . . 56, Sep 58
—heater-cathode short, Westinghouse Chassis V-2374-1 . . . . . 72, Mar 60
—plate glowing red . . 34, Aug 60
—voltage and current chart . . . . . 32, Feb 59
Precautions in making scope tests . . . . . 52, Mar 58
Resistors in output circuit . . . . . 22, Mar 58
Resistor failures, RCA Model 630-TS . . . . . 26, Jan 58
Retrace blanking, 1959 RCA sets . . . . . 50, May 59
Servicing guide by symptoms . . . . . 14, Sep 57
Snivets . . . . . 7, Mar 54
Step-by-step troubleshooting procedure . . . . . 34, Mar 60
Symptoms of specific parts failures . . . . . 28, May 60
. . . . . 25, Jul 54
Theory of operation . . 32, Feb 59
. . . . . 26, Apr 56
Waveforms . . . . . 11, Mar 54
Width
—excessive, Muntz Model 321D1N . . . . . 46, Jun 59
—insufficient . . . . . 19, Nov 53
—insufficient, Admiral Chassis 17Z3D . . . . . 82, May 60
—insufficient, RCA Chassis KCS68C . . . . . 26, Jul 58
—shrinkage, gradual, RCA Model 21T7375 . . . . 22, Apr 58
—shrinkage whenever channels are changed, Philco Chassis TV-354 . . . . . 60, Apr 60

HORIZONTAL SYNC

See also
Horizontal AFC
Horizontal oscillator
Sync
Bending . . . . . 70, Oct 58
. . . . . 16, Jan 58
. . . . . 17, Feb 57
—corrected by parabolic feedback signal, Zenith Chassis 16T20 . . . . . 17, Jul 55
—due to hum in sync signal . . . . . 34, Jun 58
—due to ungrounded AFC-tube cathode, Philco Model 52T-2256 . . . . . 24, Apr 58
—only at top of picture . . . . . 70, Oct 58
"Christmas-tree" effect . . . . . 34, Mar 60
. . . . . 56, Sep 58
. . . . . 36, Jul 58
. . . . . 29, May 53
Critical, Motorola Chassis TS-324B . . . . . 30, Jan 59
Floating from side to side, Westinghouse Model H-640T17 . . . . . 16, Dec 57
Interaction with vertical sync
—Philco Model A-T1818 . . . . . 20, Mar 58
—due to AGC trouble, Silvertone Model 5160 . . . . . 60, Apr 59
Intermittent loss
—Motorola Chassis TS-410A . . . . . 72, Mar 60
Jitter
—Admiral Chassis 24D1 . . . . . 60, Apr 60
—due to defective boost-filter capacitor . . . . . 18, Aug 58
—pulse-width circuit . . . . . 22, Apr 58
—Silvertone Chassis 456.150-22 . . . . . 22, Apr 58
Loss
—after prolonged operation, Muntz Chassis 17B4 . . . . . 68, Sep 60
—on camera changes, RCA Chassis KCS83 . . . . . 38, Oct 59
Oscillator far off frequency, Admiral Chassis 19T2 . . . . . 70, Oct 58
"Pie-crust" effect, Emerson Chassis 120144B . . . . . 34, Jun 58
Pulling
—General Electric Model 16C113 . . . . . 76, Sep 59
—how to isolate in pulse-width AFC circuit . . . . . 24, Apr 58
—possibly due to defective signal from community cable . . . . . 26, Jul 58
—Silvertone Model 9154 . . . . . 70, Oct 60
Squegging—
. . . . . 56, Sep 58
. . . . . 36, Jul 58
Unstable, due to arcing in HV cage . . . . . 34, Jun 58
Weaving, intermittent, Packard-Bell Model 2710 . . . . . 18, Aug 58

HUM

AC-DC radios . . . . . 17, Jun 55
Check list of possible causes . . . . . 5, Aug 55
General causes in radio and TV . . . . . 17, Mar 56
Hi-fi amplifier . . . . . 5, Aug 55
. . . . . 15, Apr 55
—measurement . . . . . 76, Feb 59
Magnetic cartridges . . . . . 38, Mar 59
. . . . . 17, Feb 57
Visible in sync waveforms . . . . . 28, Feb 60

HYBRID AUTO RADIOS

Intermittent operation . . . . . 50, May 59
Motorola Model 6TAS8 . . . . . 11, Jul 56
Output transistor shorted . . . . . 60, Jul 59
Power-transistor replacement guide . . . . . 38, Mar 60
Transistorized output stages . . . . . 23, Jun 57
Tube circuits . . . . . 36, Feb 59

IF SECTION OF TV

See
Video IF

INDUSTRIAL ELECTRONICS

Binary counting in computers . . . . . 40, May 58
Breaking into servicing field . . . . . 21, Sep 57
Chemical sensers . . . . 32, Feb 58
Closed-loop control systems . . . . . 32, Mar 60
. . . . . 40, Jan 60
—typical installation . . . . . 54, May 60
Decade computers . . . . 44, Jul 58
Decade counters . . . . . 24, Sep 58
Density measurement of liquids . . . . . 48, Jan 58
Dielectric heaters . . . . 30, May 59
Digital readout indicators . . . . . 44, Jul 58
Eccles-Jordan circuit . . 44, Jul 58
. . . . . 40, May 58
Filling opaque containers using automatic control system . . . . . 40, Jul 60
Flow-rate meter . . . . 52, Dec 57
Gas-glow counter tubes . 24, Sep 58
Heaters, dielectric and induction . . . . . 62, Sep 59
Heat sensers . . . . . 16, Oct 57
High-temperature measurements . . . . . 14, Nov 57
Ignitrons to control welding . . . . . 26, Dec 59
. . . . . 60, Jan 59
Induction heating . . . . 54, Aug 59
Liquid-level sensers . . . . 48, Jan 58
MBS tubes . . . . . 24, Sep 58
Magnetic amplifiers . . 26, Nov 60
. . . . . 64, Sep 60
Motor control using magnetic amplifiers . . . . . 26, Nov 60
Motor-speed control . . 30, Mar 59
Optical pyrometer . . . 14, Nov 57
Oxidation-reduction potential . . . . . 32, Feb 58
Pen positioners . . . . . 64, Nov 59
Perimeter control for rolls of newsprint . . . . . 46, Apr 58

pH sensers . . . . . 32, Feb 58
Photocells in high-temperature measuring devices . . 14, Nov 57
Power supplies, transistorized converter and inverter . . . . . 34, Feb 59
Pressure measurement . 52, Dec 57
Preventive maintenance of control systems . . . . . 32, Mar 60
Process-control principles . . . . . 40, Jan 60
Pyrometer system . . . . 54, May 60
Recording instruments . 64, Nov 59
Saturable reactors . . . . 60, Sep 60
Schematic symbols compared to radio-TV counterparts . . . . . 21, Sep 57
Silicon controlled rectifiers . . . . . 60, Sep 60
Strain gauge . . . . . 52, Dec 57
Temperature control using magnetic amplifiers . . . . . 26, Nov 60
Test equipment . . . . . 32, Mar 60
Thermistors . . . . . 16, Oct 57
Thermocouples . . . . . 16, Oct 57
Thickness measurement . 46, Apr 58
Thyratrons, "firing angle" . . . . . 60, Sep 60
—in electronic timers . 40, Nov 58
—operating theory . . . 26, Dec 59
Timers, electronic . . . . 40, Nov 58
Vibration sensers . . . . . 18, Mar 58
Viscosity sensers . . . . . 48, Jan 58
Water-distillation system . . . . . 40, Jan 60
Weld timers . . . . . 60, Jan 59

INTERCOMS

Combined with radio for built-in home installation, *Guardian Mark I* . . . . . 44, Oct 56
General principles . . . . 29, Mar 52
Installation in home . . . 19, Apr 56
Outdoor paging speaker included . . . . . 28, Jun 60
Types available for different purposes . . . . . 32, May 60

INTERFERENCE

Also see
Hum
Adding-machine interference in PA system . . . . . 20, Mar 58
Adjacent- and co-channel . . . . . 34, May 57
Broadcast-band interference, from TV sets . . . . . 46, Jun 59 . . . . . 19, Nov 51
—from various sources . 78, Sep 59
Channel 2 signal picked up on 4, 5, 9, and 13 . . . . . 56, Jun 60
Co-channel in mountainous area . . . . . 56 Sep 58
General level of RF interference in shop . . . . . 40, Feb 60
Neon sign interfering with TV reception . . . . . 68, Sep 60
Noise generated in tuners . . . . . 5, Nov 52
Police radio in TV IF band . . . . . 18, Aug 58
RF picked up by audio stage . . . . . 27, Mar 54
Shielding—magnetic and electrical . . . . . 5, Sep 54
Snivets . . . . . 34, Jun 58 . . . . . 7, Mar 54
Sound bars in picture . . 76, Sep 59
Spooks . . . . . 7, Mar 54
Sync buzz . . . . . 21, May 55
Vertical black bars in picture, Admiral Chassis 18Y4B . . . . . 84, May 60 . . . . . 76, Sep 59
—Motorola Chassis TS-52 . . . . . 14, Nov 59 . . . . . 76, Sep 59
Visible on TV screen . . 13, Sep 54

INTERMITTENT TROUBLES

AGC voltage goes highly negative, Stromberg-Carlson Chassis 622 . . . . . 60, Apr 60
Analyzing . . . . . 17, Feb 55
Audio, General Electric U line . . . . . 60, Dec 59
Detection with recording device . . . . . 17, Feb 54
Horizontal sync, Motorola Chassis TS-410A . . 72, Mar 60
Horizontal weaving, Packard-Bell Model 2710 . . . . . 18, Aug 58
Hybrid auto radio . . . . 50, May 59
Monitoring device, Seco SL-10 *Monitron* . . . . . 23, Sep 56
—Win-Tronix Model 828 *Intermittent Condition Analyzer* . . . . . 30, Oct 57
Rolling . . . . . 62, May 58 . . . . . 13, Dec 56
Sound fades during warm-up, RCA Chassis KCS90 . . . 30, Jan 59
Troubleshooting suggestions . . . . . 29, Jul 51
Vertical sweep . . . . . 44, Aug 60 . . . . . 40, Aug 59

INTERMODULATION

See under
Test equipment

KEYED AGC

Adding to 630-type chassis . . . . . 23, May 51
Bias on keying tube incorrect . . . . . 18, Aug 58
RCA Chassis KCS83 circuit . . . . . 44, Aug 60
Shorted pulse-coupling capacitor, RCA Chassis 5377 . . 60, Apr 60
Theory of operation . . . 18, Jul 56
Troubleshooting . . . . . 87, May 55
6BU8 circuits . . . . . 24, Jun 60
—Admiral Chassis 16J1 . . . . . 18, Apr 58
—Motorola Chassis TS-542 . . . . . 16, Jun 58
—Zenith Chassis 17A20 . . . . . 18, Apr 58

LOUDSPEAKERS

See
Speakers
Commercial sound

MASTER ANTENNA SYSTEMS

Basic components . . . . 26, Aug 60 . . . . . 9, Nov 56
Installation . . . . . 9, Feb 57
Planning and calculating needs . . . . . 9, Jan 57
Test-equipment needs . . 9, Dec 56
Troubleshooting . . . . . 13, Mar 57

MATHEMATICS

Binary numbers . . . . . 40, May 58
Decibel formulas and applications . . . . . 66, Aug 59 . . . . . 28, Jul 56 . . . . . 41, Mar 52
Color-signal measurement . . . . . 25, May 54
Graph interpretation . . 12, Dec 57
Impedance and reactance computations . . . . . 25, Feb 57
Impedance formulas for tuned circuits . . . . . 23, Apr 57
Modulation levels of color signal . . . . . 17, Jun 54
Nomograms . . . . . 12, Jan 58
Q, computation . . . . . 25, Mar 57
Resonant-frequency calculations . . . . . 25, Mar 57
Time constants . . . . . 27, Mar 56
Typical applications in servicing . . . . . 13, Feb 54
Vectors . . . . . 10, Dec 54

MICROPHONES

Capacitor type . . . . . 30, Oct 59
Carbon type . . . . . 42, Aug 59
Ceramic type . . . . . 30, Oct 59
Crystal type . . . . . 42, Aug 59
Directional characteristics . . . . . 25, Mar 56
Dynamic type . . . . . 30, Oct 59
Impedance matching . . 30, Oct 59
Performance characteristics, general . . . . . 42, Aug 59
Phasing in multiple installations . . . . . 52, Jan 59
Placement . . . . . 30, Oct 59
Ribbon type . . . . . 30, Oct 59
Specifications of various types . . . . . 30, Oct 59 . . . . . 42, Aug 59
Types compared . . . . . 30, Oct 59 . . . . . 42, Aug 59 . . . . . 16, Feb 56

MODULES

See also
Printed component combinations
Emerson TV Chassis 120306 . . . . . 19, Feb 57
Experimental application in TV receiver . . . . . 20, Aug 55
Portable-radio application . . . . . 44, Oct 56
Testing and repair . . . . 36, Jan 60 . . . . . 10, Oct 55

MULTIMETERS

See
Voltmeters
VOM's
VTVM's

NO RASTER or NO PICTURE

See
High voltage
Picture tube

NOISE INVERTERS

Emerson Model 748B, keyed type . . . . . 20, Oct 57
Motorola *Frame-Lock* in Chassis TS-609 . . . . 15, Nov 55
Stromberg-Carlson Model 621 . . . . . 20, Oct 57
Sylvania Chassis 1-522-2 . . . . . 19, Jun 55
Sylvania Chassis 1-543-1 . . . . . 48, Aug 59
3CS6, Sylvania Chassis 1-537 . . . . . 19, Apr 57
6BU8 . . . . . 29, Jun 56

OLD-TV RESTORATION

Admiral Model 21F1 . 24, Dec 60
Admiral Model 36X36 . 8, Aug 58
Bendix Model 6003 . . . 22, Jun 59
Business angle—is set worth it? . . . . . 40, Feb 60
Capehart CX-33 series . 22, Apr 59 . . . . . 30, Feb 59
DuMont RA-109 . . . . 32, Oct 60
Emerson 700 series . . . 38, Feb 60 . . . . . 32, Oct 59
General Electric Model 16C103, 17T1, and similar . . 28, Apr 60
Life expectancy of average TV set . . . . . 44, Jun 59
Magnavox Chassis CT331 . . . . . 22, Jun 59
Philco Model 51T1836 series . . . . . 24, Oct 58
RCA Chassis KCS47 . . 22, Apr 59 . . . . . 16, Dec 58
Zenith Chassis 19K23 . 24, Aug 60

OSCILLOSCOPES

See also
Waveforms
Amplifier circuits . . . . . 12, Jun 56
Attenuator-network adjustments . . . . . 23, Nov 56
Beam speed . . . . . 30, Nov 55
Calibration . . . . . 32, Dec 57 . . . . . 21, May 54
Checking performance . 15, Mar 54
Color-servicing requirements . . . . . 15, Feb 56
DC amplifiers . . . . . 11, Aug 54
—applications in troubleshooting . . . . . 70, Aug 59
Depth of case . . . . . 50, May 59
EICO kit Model 460 . . 70, Feb 59
Evaluating design features . . . . . 25, Dec 56
External sync for analyzing horizontal pulling . . . 29, Sep 52
FM-radio signal-tracing uses . . . . . 19, Sep 53
Frequency-response specifications . . . . . 28, Jul 56
General information . . 10, Nov 55
Hickok Model 685 . . . 38, Nov 57
Hickok Model 675 . . . 23, Sep 56
Hickok Model 770 . . . 19, Sep 55
Hickok Model 665 . . . . 6, Feb 54
Hycon Model 622 . . . . 23, Mar 57
Hycon Model 617 . . . . 19, Sep 55
Impedance of test circuit, effect on scope indication . . . . 14, Apr 58
Jackson Model CRO-2, late-production features . . 13, Jun 54
—sync-polarity reversal . . . . . 31, Apr 54
Lissajous-pattern analysis . . . . . 14, Oct 56 . . . . . 11, Aug 54
Low-capacitance probe use . . . . . 28, Sep 59 . . . . . 28, Nov 58 . . . . . 20, Mar 56
Maintenance . . . . . 23, Nov 56
Operating instructions, step-by-step . . . . . 26, Oct 58
PACO kit Model S-50 . 52, May 58
Power-supply circuits . . 12, Jan 56
Precision Model ES-550 . . . . . 10, Dec 55
Probe scope Model PO-1 (1" screen) . . . . . 17, Aug 55
RCA Model WO-33A . 48, Jul 60
Requirements in sweep-circuit testing . . . . . 52, Mar 58
Rise time defined . . . . 15, Oct 54
Simpson Model 466 *Handiscope* . . . . . 44, Aug 58
Simpson Model 548 *Colorscope* . . . . . 20, Mar 56
Special features . . . . . 20, Jul 56
Sweep circuits . . . . . 26, Feb 56
—adjustments . . . . . 23, Nov 56
Sylvania Type 403 . . . 19, Jan 55
Synchronizing . . . . . 20, May 56 . . . . . 6, Feb 54
Uses in radio-TV shop . . 7, Jul 53
Waterman S-16-A *Craftscope* . . . . . 52, Dec 59
"Writing speed" defined . . . . . 23, Sep 56
120-cps sweep for alignment . . . . . 51, Oct 51

PA SYSTEMS

See
Commercial sound

PHONOGRAPHS, SPECIAL TYPES

Automobile type, CBS *Highway Hi-Fi* . . . . . 29, Apr 56 . . . . . 23, Mar 56
Output fed into radio on RF carrier, Motorola Model 53F2 . . . . . 25, Feb 54
Transistorized portable, Regency Model TR-22 and RP-3 . . . . . 28, May 59
—Rockland . . . . . 60, Mar 58

PICTURE SYMPTOMS

See under appropriate sections of TV receiver (video IF, vertical sweep, etc.)
Also under Interference

PICTURE TUBES

See also
Conversion to larger picture-tube size
Aluminized types . . . . . 36, Jan 57
Arcing, internally . . . . . 50, May 59
—to ground strap . . . . . 72, Mar 60

Base replacement . . . . . 15, Jun 56
Blue glow in neck . . . . 72, Oct 60
Brighteners . . . . . 28, Sep 60
Brightness maximum and uncontrollable, Hallicrafters Chassis A1400D . . . . . 60, Dec 59
Check tube for bench, 5AXP4 . . . . . 17, Jan 55
—90° 8XP4 . . . . . 23, Jun 56
—110° 8YP4 . . . . . 32, May 58
Checking cathode and grid circuits . . . . . 28, Oct 60 . . . . . 26, May 60
Color . . . . . 6, Jan 54
Contrast and brightness problems . . . . . 26, Oct 59
Contrast poor, Motorola Model 17T22 . . . . . 60, Dec 59
Damaged by prolonged operation with no vertical sweep . . . . . 38, Aug 57
Dark, but high voltage present . . . . . 26, May 60
Electrostatic focus . . . . 19, Jul 51
Horizontal retrace blanking, 1959 RCA sets . . . . . 50, May 59
Ion-trap magnet, unusually far back . . . . . 34, Jun 58
—replacement . . . . . 26, Jan 58
Installing cabinet-mounted unit . . . . . 25, Feb 55
Kills high voltage when installed . . . . . 44, Mar 59
Letting in air for disposal . . . . . 35, Jul 53
Long warm-up, 30 minutes or more . . . . . 26, Jan 58
Low-Eg2 types . . . . . 22, Aug 58
Metal type, arcing and corona prevention . . . . . 40, Nov 56 . . . . . 29, Jan 56
—replacement with all-glass types . . . . . 70, Oct 58 . . . . . 18, May 58
Negative picture . . . . 30, Oct 60
Post-acceleration color tube . . . . . 25, Jan 56
Rejuvenating . . . . . 28, Sep 60
Scalloped corners in raster, not due to neck shadow . . . . . 38, Oct 59
Servicing guide by symptoms . . . . . 17, Nov 55
Setup adjustments . . . . 14, Apr 57
Shading from left to right in raster, Philco Model 53T1827 . . . . . 60, Apr 59
Spark gap to protect 110° tube . . . . . 50, Jul 59
Spot elimination . . . . . 56, Feb 59 . . . . . 29, Sep 52
Substitution chart . . . . . 59, May 51
Substitution unit, Tele-Check Model CR-99 . . . . . 23, Sep 56
Tripotential-focus 110° type . . . . . 48, Aug 59
Trouble diagnosis . . . . . 7, May 53
Unusual troubles . . . . 26, Apr 58
Welding open elements . . . . . 28, Sep 60
X burn on screen . . . . . 15, Jun 56
X-ray hazard investigation . . . . . 26, Dec 60
110°, bases . . . . . 22, May 58
—design features . . . . 19, Apr 57

PICTURE-TUBE TESTER

See
CRT Tester

PORTABLE RADIOS

See also
Transistor radios

Connection to hi-fi system . . . . . 82, May 60
Modular construction . . 44, Oct 56
Pocket type with subminiature tubes, Motorola Model 54L1 . . . . . 25, Nov 54
Servicing tips . . . . . 31, Jul 52
Tubes, 1-volt, frequent failure . . . . . 32, May 58

PORTABLE TV

Admiral 10" Chassis 14YP3B . . . . . 14, Dec 56
Disassembly of typical units . . . . . 28, Dec 59
Emerson 8" combination, Model 1232 . . . . . 19, Feb 57
General Electric 9" Model 9T001 . . . . . 27, Mar 57
General Electric Model 14T007 . . . . . 9, Oct 55
RCA 8" Chassis KCS100B . . . . . 21, Aug 56
Sylvania *dualette*, Chassis 1-543-1 . . . . . 48, Aug 59
Sylvania 17", 110° Chassis 1-537 . . . . . 19, Apr 57

POWER LINE

Short to chassis due to component breakdown, Setchell-Carlson Model 71 . . . . . 58, Nov 58
Voltage adjuster . . . . . 17, Sep 55
Voltage fluctuations, effect on TV . . . . . 36, Oct 60

POWER SUPPLIES

AC input to 5U4's insufficient . . . . . 70, Oct 58
Audio output tube as dropping resistor in B+ supply . . . . . 56, Sep 58 . . . . . 26, Feb 58 . . . . . 54, Oct 56
B-minus supply troubles . . . . . 46, Feb 57
B+ delay feature, Motorola *Tube Sentry* . . . . . 24, Oct 57
B+ voltage-divider networks . . . . . 31, May 56
Bias supply, Precision Apparatus Model 230 . . . . . 36, Jul 57
Construction project, for hi-fi system . . . . . 27, Jun 54
DC source for auto-radio servicing . . . . . 43, Nov 53
Decoupling between branches of B+ line . . . . . 36, Jan 59
Full-wave doubler . . . . 38, Oct 59
Half-wave doubler . . . 36, Jan 59
Half-wave, 133-volt supply in TV sets . . . . . 22, Jul 57
Low-ripple bench supply for transistor servicing, ATR Model 610C-EL1F . . 30, Jan 58
—EICO Model 1020 . . 52, Aug 59
—Electro Products Model PS-2 . . . . . 60, Sep 58
—Perma-Power Model A-400 . . . . . 38, Nov 57
—Seco Model PS-2 . . . 56, Oct 58
—Sencore Model PS-103 . . . . . 50, Jun 59
Low-voltage (B+), step-by-step troubleshooting procedure . . . . . 24, Nov 59
—theory of operation . . 36, Jan 59
Miniature type, authorized *Multivolter* . . . . . 19, Mar 55
Misconnected branch in B+ system . . . . . 76, Nov 60
Operating characteristics, general . . . . . 21, Jul 52
Power factor . . . . . 23, Nov 55
Rectifier tube, frequent burnout . . . . . 72, Mar 60
—type interchanging . . 21, May 51
Ripple level normal for TV . . . . . 48, Feb 60
Transistorized converters and inverters . . . . . 34, Feb 59
Voltage dividers in B+ circuit . . . . . 31, May 56
Voltage multipliers . . . 21, Jul 52

PREVIEWS OF NEW SETS

Admiral Chassis 15B3 (Model PS 17F22) . . . . Aug 59
—Chassis 16H1 (Model P14D11) . . . . . Nov 57
—Chassis 18A6 (Model T21G2) . . . . . Sep 58
—Chassis 20H7 and 3S1 (Model ST24M72) . . . . Jan 60
—Chassis 20S6 (Model L22M23) . . . . . Apr 60
—Chassis 20T6 (Model TS-22M41) . . . . . Jul 60
—Chassis 20UB6C (Model CH21UH33) . . . . . Mar 59
—Chassis 25B6 (Model L71N57) . . . . . Sep 60
Airline Model WG-4082A . . . . . Dec 59
—Model WG-5041A . . . . Nov 57
—Model WG-5062B . . . . Feb 59
—Chassis V2365-5 (Model GTM4201A) . . . . . Sep 58
Andrea Model VQ21 . . . . Nov 57
—Chassis VQ21-110 (Model MLB-VQ21) . . . . . Nov 58
—Chassis VR-121 (Model T-VR121) . . . . . Jun 59
—Chassis VS-323-1 (Model 2LBVS-323-1) . . . . . Jul 60
Curtis Mathes Model 1121 . . . . . Jan 60
DuMont Chassis RA502 (Model "Northfield 21") . . . . . Feb 59
—Chassis RA-601A (Model "Colony") . . . . . Jul 60
Emerson Model 1280 . . . . Nov 57
—Chassis 120451H (Model 1506) . . . . . Jul 59
—Chassis 120507A (Model 1524) . . . . . May 60
—Chassis 120526C (Model 1610) . . . . . Aug 60
Fleetwood Tuner Chassis 870 (Model 900) . . . . . Sep 59
General Electric Chassis M5 (Model 21T3421) . . . . Nov 59
—Chassis M6 (Model R740 VWD) . . . . . Oct 60
—Chassis Q2 (Model 14P1210) . . . . . Nov 57
—Chassis U3 (Model 21C2550) . . . . . Dec 58
—Chassis U4 (Model 21C3580) . . . . . Feb 60
Hoffman Chassis 335(Model M1277) . . . . . Apr 59
—Chassis 341 (Model SP3531) . . . . . Dec 58
—Chassis 344 (Model K1331) . . . . . Sep 59
—Chassis 350 (Model B-3683) . . . . . Mar 60
—Chassis 355 (Model K1919) . . . . . Nov 60
—Chassis 422 (Model M3357) . . . . . Nov 57
—Chassis 426 and 1139 (Model M3703) . . . . . Aug 60
Hotpoint Chassis U2 (Model 21S406) . . . . . Nov 57
Magnavox Chassis 182 (amp), Chassis 54-03AA (radio) (Model 1ST204H) . . . . Jan 59
—Chassis U28-04-11 (Model U163L) . . . . . Sep 60
—Chassis U30-15-00 (Model IU 354R) . . . . . Sep 59
—Chassis V-29-12-11 (Model 1MV188L) . . . . . Mar 60
—Chassis V29-0500 . . . . . Jul 59
—Chassis V30-05AA (Model 2MV-147L) . . . . . Apr 59
—Chassis V34-01-00 (Model 1MV139D) . . . . . Nov 60
Motorola Chassis PTS-546Y (Model Y21P1B) . . . . . Oct 58
—Chassis RTS-544 (Model 21K100MA) . . . . . Jan 59
—Chassis TS-430 (Model 17T32BZ) . . . . . Mar 59
—Chassis TS-432 (Model 19P1) . . . . . Dec 60
—Chassis TS-433 (Model 17P6) . . . . . Oct 59
—Chassis TS-542A (Model 21T377) . . . . . Nov 57
—Chassis TS-558 (Model 21K131CW) . . . . . Jan 60
—Chassis TS-564 (Model 21C10CW) . . . . . May 60
—Chassis TS-568 (Model 23K30M) . . . . . Oct 60
—Chassis WTS-553 (Model A21K106B) . . . . . May 59
Muntz Chassis "J" (Model 17PS) . . . . . Feb 59
—Chassis "J" (Model 21TM) . . . . . Apr 59
—Chassis T3707 (Model 21CP-3M) . . . . . Jun 60
—Model 21LTS . . . . . Aug 59
Olympic Chassis GT . . . . . Nov 57
—Chassis HB (Model TB131) . . . . . Oct 58
—Chassis HY (Model TY134) . . . . . Dec 59
—Chassis JRW (Model TRW203M) . . . . . Apr 60
—Chassis JV (Model 7TV11M) . . . . . Sep 60
Packard-Bell Chassis 98D3 (Model 21DC6) . . . . . Nov 57
—Chassis 98D4 (Model 21CD9) . . . . . Oct 58
—Chassis 98D8 (Model 23DK1) . . . . . Jul 60
—Chassis TVP-2, TVT-2, 7TV-3 (Model 21K2) . . . . . Feb 60
Philco Chassis 8L41 (Model F4212) . . . . . Nov 57
—Chassis 9H25U (Model UG3050GL) . . . . . Dec 58
—Chassis 9L38U (Model UG-4710L) . . . . . May 59
—Chassis 9L60 (Model G4240) . . . . . Sep 58
—Chassis 10AT10 (Model H2010L) . . . . . Feb 60
—Chassis 10L32 (Model H4673MR) . . . . . Aug 60
—Chassis 10L43 (Model H-3412L) . . . . . Nov 59
—Chassis 10L60 (Model H-4686S) . . . . . May 60
—Chassis 11N51 (Model J-3702L) . . . . . Oct 60
RCA Chassis CTC9A (Model 210CK855) . . . . . Sep 59
—Chassis KCS111D (Model 14PD8053U) . . . . . Nov 57
—Chassis KCS117A (Model 21PT9095) . . . . . Apr 59
—Chassis KCS121E (Model 21D9475) . . . . . Sep 58
—Chassis KCS122BAB (Model 21RT9655) . . . . . Nov 58
—Chassis KCS124C . . . . Dec 59
—Chassis KCS126A (Model 170P048) . . . . . Jul 59
—Chassis KCS127A (Model 210T195) . . . . . Oct 59
—Chassis KCS127AE (Model 240-KV-775SU) . . . . . Apr 60
—Chassis KCS130M (Model 171-AR-067) . . . . . Oct 60
—Chassis KCS132ZH (Model 231-BE-627) . . . . . Dec 60
Setchell-Carlson Chassis C105 (Model P65) . . . . . Dec 58
—Chassis C106 (Model P66) . . . . . Feb 60
—Chassis 159 (or Z159) (Model 21C159) . . . . . Jun 59
Silvertone Chassis 528.51160 (Model 8190) . . . . . Nov 57
—Chassis 528.51400

(Model 9160) ..... Oct 58
—Chassis 528.51550
(Model 9105AQ) .... Jan 59
—Chassis 528.51643
(Model 118.5 CH-A) .. Nov 59
—Chassis 528.51660
(Model 106DS) ..... Jun 60
—Chassis 528.51680
(Model 1118CH) .... Nov 60
Sonora Model LB-2159 .. May 59
—Chassis 1150-100
(Model S60T211) .... Aug 60
Sylvania Chassis 1-537-5
(Model 17P110SU) ... Mar 59
—Chassis 1-540-1
(Model 21C407M) ... Nov 57
—Chassis 1-541-9
(Model 23S24M) ..... Jan 60
—Chassis 1-542-3
(Model 21T218) ..... Nov 58
—Chassis 1-543-1
(Model 17D203Q) .... Jun 59
—Chassis 1-544-1
(Model 23T14M) .... Mar 60
Trav-Ler Chassis 750-19
(Model 1770U) ..... Aug 59
—Chassis 943-38 (Model
721-K-751) ..... Mar 59
—Chassis 1051-19 (Model
821T901) ..... Nov 59
—Chassis 1150-29(Model
921-K-810) ..... May 60
—Chassis 1150-80 (Model
23MT6055) ..... Dec 60
V-M Model 571..... Feb 59
Westinghouse Chassis V-2365-11
(Model H-17C287) .... Jun 59
—Chassis V-2366-1 (Model
H-21T217) ..... Jan 59
—Chassis V-2372 (Model
H-21T219A) ..... Nov 57
—Chassis V-2374-1 (Model
H21T263) ..... Oct 59
—Chassis V-2375-1 (Model
H21K272) ..... Aug 59
—Chassis V-2378-6 (Model
H-K4600) ..... Apr 60
—Chassis V-2384-2 (Model
H-P3300U) ..... Jun 60
—Chassis V-2389-3 (Model
H-K4410) ..... Dec 60
Zenith Chassis 16C20 (Model
C1715L) ..... May 59
—Chassis 16D25Q (Model
2010C) ..... Mar 60
—Chassis 16E21Q (Model
E3002W) ..... Sep 60
—Chassis 16F25Q (Model
F2215L) ..... Nov 60
—Chassis 17D20 (Model
D2464L) ..... Dec 59
——Chassis 18C20Q (Model
C3014R) ..... Oct 59
—Chassis 18E20 (Model
E2755W) ..... Jun 60
—Chassis 19A20 (Model
A2330H) ..... Nov 57
—Chassis 19B20UD (Model
B2330EUD) ..... Nov 58
—Model C3004E ..... Jul 59

PRINTED COMPONENT COMBINATIONS

See also
Modules
Construction ..... 11, Nov 52
Erie PAC modules ... 23, Apr 56
Schematics of popular types
..... 24, Apr 59

PRINTED-WIRING BOARDS

Admiral radio, Chassis 5C3
..... 33, May 53
Broken-board repair ... 36, Nov 56
Circuit-tracing ..... 34, Jan 60
..... 23, Dec 56
Component identification
..... 34, Jan 60
—replacement ..... 11, Sep 56
..... 10, Jan 56
Components especially designed
for ..... 19, Feb 56
Construction details ... 46, Oct 58
..... 13, Aug 56
Dangers of careless workmanship
when repairing ..... 34, Jan 60
IF strip, RCA ..... 15, Nov 55
..... 25, Feb 54
Miscellaneous service hints
..... 26, Dec 58
Motorola *Placir* in radio,
Model 52R ..... 35, Sep 52
Painted lines and symbols as
service aids ..... 30, May 60
Removal from chassis .. 20, Oct 56
Repair ..... 15, Jan 55
Service case histories .. 46, Oct 58
Solder-pot usage ..... 12, Feb 56
Test-equipment connections
..... 34, Jan 60
..... 23, Dec 56
Unbonded-conductor repair
..... 36, Nov 56
Unsoldering components
..... 11, Sep 56
—with special pencil irons
..... 48, Sep 58

PROBES

See
Test probes

RADIO

See also
Auto radios
Hybrid auto radios
Portable radios
Signal-seeking auto radios
Transistor radios
Tuners, FM and AM-FM
AC-DC, receiver troubles
..... 4, Jul 52
—rectifier troubles .... 19, Mar 51
Aligning AC-DC superhet
..... 14, Mar 57
Book radio, Crosley Model
JM-8WE ..... 23, Mar 56
Clock-unit repairs for clock-radios
..... 32, Jul 59
Distorted output ..... 60, May 58
FM table models ..... 28, Nov 60
Foreign-made radios ... 13, Jul 56
Frequency drift ..... 23, Jun 55
Heterodyne whistle filter
..... 23, Apr 54
Hum in AC-DC models
..... 17, Jun 55
Interference, from TV sets
..... 46, Jun 59
..... 19, Nov 51
—from various sources
..... 78, Sep 59
Localizing troubles quickly in
AC-DC units ..... 64, May 60
..... 44, Mar 60
Oscilloscope tests ..... 9, Jul 53
Pocket portable with subminiature
tubes, Emerson Model 747
..... 29, Jan 54
Portable-radio servicing
..... 18, Apr 54
Rectifier-tube burnout in
AC-DC unit ..... 56, Feb 59
Tractor radio, Automatic
Model TR-12 ..... 29, Jan 54
Tracking superhets .... 24, Dec 57
Tubes most widely used
..... 34, Jul 60
Turret tuner in multiband
Hallicrafters Model TW-2000
..... 15, Dec 54
Voltage analysis ..... 64, May 60
Westinghouse Model H-381T5
..... 23, Jul 53

RECORD CHANGERS

Adjustments, general .. 14, May 56
..... 12, Apr 56
Admiral Model RC607 . 20, May 58
Collaro *Conquest* ..... 20, May 58
Garrard RC 121/4 ... 26, Sep 58
Monarch UA-8 ..... 26, Sep 58
Muting switch RCA
Model 3-HES-5 .... 52, Nov 59
Noise from hi-fi speakers when
automatic-shutoff device
operates ..... 60, Apr 59
Service hints ..... 38, Mar 59
..... 20, May 58
..... 13, Jan 54
..... 27, Sep 53
Speed problems ..... 48, Dec 60
V-M Model 1200A ... 20, May 58
Webcor Model 151 ... 26, Sep 58
Zenith Model S-14086 . 26, Sep 58

REJUVENATORS

See
CRT Testers

REMOTE CONTROL, TV

Admiral *Son-r* ..... 60, Mar 58
Douglas Model 327 ... 31, Mar 54
Fleetwood Model 600 .. 23, Jul 53
General Electric RF type
..... 26, Sep 59
Hoffman RF *Beam Rider*
..... 50, Nov 57
Kaye-Halbert Model 263
..... 23, Sep 53
Motorola RF-type *Transituner*
..... 21, Mar 57
RCA Wireless Wizard 28, Jan 59
Regency Model RT-700
..... 21, Feb 55
Remot-O-Matic ..... 21, Feb. 55
Sentinel Model 21121T
..... 17, Jan 56
Tech-Master *Duo-Master*
..... 44, Dec 57
Westinghouse *Picture Pilot*
..... 50, Nov 57
Zenith *Space Command*
..... 21, Mar 57

RESISTORS

See also
Fusible resistors
Printed-wiring board mounting
..... 19, Feb 56
Series-string heater dropping
..... 32, May 59
..... 15, Nov 55
..... 23, Jul 54
Special applications in horizontal
sweep stages ..... 22, Mar 58
Special types used in TV sets
..... 21, Feb 57
Stock of most popular types
..... 29, May 57
Surgistors ..... 30, Apr 60
Types, characteristics, applications
..... 19, Oct 54

SELENIUM RECTIFIERS

Plug-in type ..... 17, Aug 54
—conversion to ..... 19, Jul 55
Ratings and characteristics,
general ..... 19, Oct 56
Replacement with higher current
rating ..... 46, Jun 59
Stock for home service calls
..... 23, Jul 54
Testing ..... 43, Jul 53
..... 4, Jan 51

SERVICE AIDS

Check tube, 5AXP4 .. 17, Jan 55
—8XP4 ..... 23, Jun 56
—8YP4 ..... 32, May 58
Chemicals ..... 29, Mar 56,
—chart of available types
..... 34, Sep 60
Dolly for loading TV's onto
station wagon ..... 19, Feb 54
Extension leads for servicing
cabinet-mounted CRT
..... 25, Nov 51
Plastic "squeeze bottles" as
insulators ..... 60, Oct 60
Small-parts cabinets .. 25, Apr 54
Special-purpose tuner tools
..... 23, Jul 54
Troubleshooting light .. 27, Mar 54

SERVICING AT BENCH

Antenna-system requirements
..... 30, Jul 58
Chassis cradle ..... 30, Oct 58
Circuit analysis without a
schematic ..... 4, Jul 52
CircuiTrace information on
schematics ..... 48, Sep 58
Cleaning chassis ..... 9, Aug 56
"Dogs"—tackling repair
..... 38, Feb 58
"Do-it-yourselfer" as trouble
source ..... 30, Mar 58
Efficient handling of sets
..... 34, Nov 58
..... 16, Jul 57
Finding service data for receiver
not indexed ..... 33, Dec 55
Fire under chassis, clean-up after
..... 60, Jun 60
High-frequency stray "circuits"
not shown on schematics
..... 58, Oct 59
Hinged control-panel cover,
replacement ..... 30, Sep 56
Hot-chassis safeguards . 60, Dec 59
..... 54, Jun 59
..... 18, Mar 57
—isolation networks ... 44, Mar 59
Identifying unknown TV chassis
..... 33, Dec 55
..... 19, Nov 52
..... 7, Sep 52
Isolation transformer, why needed
when working on AC-DC set
..... 60, Dec 59
Keeping record of troubles fixed
..... 5, Jun 54
Key test points in TV receivers
..... 5, May 53
Methodical troubleshooting
procedure ..... 28, Oct 60
..... 24, Sep 59
Model and chassis identification
..... 15, Nov 54
Precautions in replacing RF-IF
components ..... 23, Oct 55
Radiation-hazard investigation
..... 26, Dec 60
Rivet removal from chassis
..... 10, Jun 56
..... 43, Nov 52
Saving time in analyzing troubles
..... 24, Nov 59
Service data, uses for .. 28, Mar 60
Servicing approach for unfamiliar
circuits ..... 5, Sep 53
Signal injection using second set
as signal source ..... 18, Mar 59
Starting screws ..... 30, Sep 56
Summer service problems
..... 19, Jul 55
Test-pattern analysis ... 8, Mar 54
Test-stand construction project
..... 26, Jun 57
Troubleshooting method, general
..... 28, Oct 60
..... 24, Sep 59
..... 4, Mar 51
Voltage readings compared with
service data ..... 32, Oct 56
Wafer-switch circuit-tracing
..... 38, Apr 57

SERVICING IN HOME

Cabinet touch-up ..... 23, Jun 55
Chassis removal, TV .. 13, Jun 55
Control cleaning ..... 15, Dec 55
Difficult jobs completed on
home calls ..... 21, Aug 57
Equipment needed, for caddy
..... 14, Nov 56
—for truck or station wagon
..... 29, Jan 55
Estimating service charge, from
preliminary analysis . 34, Sep 58
—on basis of simple in-home
tests ..... 81, Oct 57
Hi-fi system ..... 34, Feb 60

ortable service bench . 15, Jun 56
Pulling chassis—when to do . . . . . 9, Nov 55
Safety-glass removal from TV using plunger . . . . . 40, Nov 56
Synchroguide adjustment . . . . . 29, Jun 57
Tube Substitution Guide . . . . . 46, Oct 60 . . . . . 22, Jun 58 . . . . . 9, Aug 56
Water under TV receiver . . . . . 29, Jan 56

SHOP EQUIPMENT

AC outlet strips for bench . . . . . 48, Jan 60 . . . . . 26, Apr 58
Auto-radio specialty . . . 38, Aug 60 . . . . . 37, Apr 54
Cabinet construction . . 24, Nov 55
Mobile shop in delivery van . . . . . 9, Nov 53
Wire . . . . . 14, Feb 58

SIGNAL GENERATORS, AUDIO

Precision Apparatus Model E-310 . . . . . 46, Aug 60
RCA Model WA-44A . 15, Mar 54

SIGNAL GENERATORS, RF

Calibrated output (in microvolts) . . . . . 5, Jun 55
Calibration and checking . . . . . 5, Sep 52
EICO Model 324 . . . . . 13, May 56
Loop antenna to radiate signals into receivers . . . . . 72, Mar 60
Performance checks . . . 5, Jul 54
Philco Model 7200 . . . 50, Mar 59
RCA Model WR-49A . 15, Mar 54
Triplett Model 3432-A . 24, Oct 55
Uses . . . . . 17, Mar 55

SIGNAL INJECTION

See
Signal-Substitution Testers

SIGNAL-SEEKING AUTO RADIOS

Aircastle Model 610. FE-153 . . . . . 23, Apr 54
Cadillac Model 7264165 . . . . . 25, Oct 54
Delco Series F2 search mechanism . . . . . 44, Aug 57
Mopar Models 902, 903 . . . . . 29, May 55

SIGNAL-SUBSTITUTION TESTERS

Applications in troubleshooting . . . . . 18, Mar 59
B & K *Television Analyst*, Model 1075 . . . . . 40, Jun 58
—Model 1000 . . . . . 36, Jul 57
Hickok *Video Scanner* . 42, Mar 58
Hickok Model 650 Videometer . . . . . 7, Jul 52
—conversion for color . 31, Apr 54
—for color convergence . . . . . 13, Jun 54
Sencore Model HG104 *Harmonic Generator* . . . . . 70, Oct 59
Use in locating defective components . . . . . 22, Sep 58
Win-Tronix Model 820 *Dynamic Sweep Circuit Analyzer* . . . . . 10, Feb 56

SILICON RECTIFIERS

Characteristics . . . . . 32, Mar 59 . . . . . 13, Jan 57
Series-resistor requirements . . . . . 54, Dec 60
Substitution for seleniums . . . . . 32, Mar 59
—experimental installations . . . . . 13, Jan 57
—Motorola Chassis TS-602YA . . . . . 72, Mar 60

SOUND DETECTORS, TV

See also
Sound section of TV
Component failures . . . 25, Jun 54
Delta type in General Electric Chassis Q3 . . . . . 40, Jul 58
Discriminator operating theory . . . . . 22, Dec 59 . . . . . 23, Jan 56 . . . . . 7, Jun 54
Drift in frequency, Olympic Chassis GD . . . . . 72, Mar 60
Gated-beam . . . . . 19, Dec 56 . . . . . 7, Jun 54
Ratio-detector operating theory . . . . . 22, Dec 59 . . . . . 7, Jun 54
Service hints . . . . . 22, Dec 59
Step-by-step troubleshooting procedure . . . . . 32, Sep 60
Volume affected by contrast control due to detector fault . . . . . 32, Nov 57
6BN6 circuit . . . . . 19, Dec 56 . . . . . 7, Jun 54
6DT6 locked-oscillator circuit . . . . . 19, Dec 56

SOUND SECTION OF TV

Alignment and servicing . . . . . 13, Jul 54
Audio amplifiers, step-by-step troubleshooting procedure . . . . . 24, Nov 59
—trouble affecting low B+ . . . . . 54, Oct 56
Buzz caused by vertical sweep . . . . . 46, Dec 58
Conversion from split sound to intercarrier . . . . . 38, Nov 56 . . . . . 31, Nov 54
—General Electric Model 810 . . . . . 22, Apr 58
Fading of sound during warm-up, RCA Chassis KCS90 . . . . . 30, Jan 59
Garbling due to trouble in voltage-divider type of output stage . . . . . 56, Sep 58
Headsets connected to TV audio . . . . . 11, Sep 54
Hi-fi system connected to TV audio . . . . . 76, Sep 59 . . . . . 30, Jan 59
Improving quality of audio . . . . . 4, May 51
Intermittent audio, General Electric U line . . . . . 60, Dec 59
Multiple speakers . . . . . 22, Nov 58
Nonintercarrier sets listed . . . . . 115, May 53
Olympic Model 945, audio section . . . . . 27, Nov 51
Sound IF, circuits . . . . . 15, May 54
—step-by-step troubleshooting procedure . . . . . 32, Sep 60
Squeal when set is turned off, Trav-Ler Model 1722 . . . . . 44, Aug 60
Sync buzz . . . . . 21, May 55
Troubleshooting . . . . . 13, Oct 54

SPEAKERS

Basic construction . . . . 20, Jun 58 . . . . . 40, Apr 58
Crossover network
—coil construction . . . 21, Jun 56
—for three-way system . 46, Jun 59
—on separate chassis . . 25, Aug 54
Choosing right speaker for job . . . . . 29, Dec 55
Coaxial types . . . . . 45, May 53
Damping . . . . . 28, Jun 59
Horn-type . . . . . 38, Aug 58
Impedance mismatch . . . 4, Nov 51
PA types . . . . . 38, Mar 57
Remote TV speakers . . 56, Jan 60
Three-way system . . . . 46, Jun 59
Universal substitute, for TV work . . . . . 29, Apr 54

SPEAKER ENCLOSURES

Design requirements . . . 31, Feb 55
RCA type usable as bass-reflex unit or corner horn . . 44, Aug 57
Reflex enclosure for 8" speaker . . . . . 11, May 53
Types in common use . . 43, Mar 53

SPECIAL EQUIPMENT

Air-conditioner servicing . . . . . 36, Jun 59 . . . . . 30, Apr 59 . . . . . 28, Aug 58
Autronic-Eye . . . . . 108, Jul 53
Electric-blanket controls . . . . . 82, May 60
Electronic organs, "cipher" symptom . . . . . 76, Nov 60
—general servicing . . . 54, Jul 59
Film-strip projector sound section . . . . . 29, Jul 54
Geiger counters . . . . . 12, Oct 55
Medical amplifiers . . . . 64, Oct 59
Message repeater . . . . . 13, May 54
Radiation detectors . . . 12, Oct 55
Radio direction finders for boats . . . . . 50, Apr 60
Small-appliance servicing . . . . . 12, Aug 58

SQUARE-WAVE GENERATORS

Audio-amplifier test applications . . . . . 32, Apr 60 . . . . . 25, Feb 55
Precision Apparatus Model E-310 . . . . . 46, Aug 60
RD Instruments Model 1715 . . . . . 52, Dec 59
Video-amplifier testing . 36, Dec 58

STEREO

Basic description of 45/45 disc system . . . . . 10, Jul 58
Basic principles . . . . . 47, Nov 53
Cartridges, specifications . . . . . 10, Jul 58
CBS "two-way" amplifier circuit . . . . . 26, Mar 59
Center-bass systems . . . 30, Jan 60
Considerations in converting from monophonic to stereo . . . . . 10, Jul 58
Preamp features, general . . . . . 38, Aug 58
"Three-channel" circuits . . . . . 30, Jan 60
Zenith *Extended Stereo* system . . . . . 30, Jan 60

SWEEP-CIRCUIT TESTER

See
Flyback Tester

SWEEP GENERATORS

Color-servicing requirements . . . . . 15, Feb 56
EICO Model 368 . . . . . 30, Jan 58
Extending frequency range covered . . . . . 21, May 54
Fine points of use in alignment . . . . . 4, Nov 51
Flatness of frequency response in service-type units . . . 20, Mar 58
Gain measurement in IF stage . . . . . 28, Mar 59
Hickok Model 615 . . . . 40, Jun 58
Hickok Model 695 . . . 38, Apr 54
Hints on use . . . . . 21, May 54
Methods used to produce sweep signal . . . . . 21, May 54
Performance requirements for TV . . . . . 11, Oct 54
Precision Model E-400 . 30, Nov 55
Radio City Products Model 780 . . . . . 19, Sep 55
Tuner response check . . 28, Mar 59
Video-sweep application to color receivers . . . . . 13, May 55

SYNC

See also
Horizontal sync
Sync separator
Vertical sync
Amplifier circuits . . . . . 30, Mar 60
—ahead of separator . . 20, Oct 57
Blanking bar as aid in isolating trouble . . . . . 74, Aug 59 . . . . . 24, Jan 59 . . . . . 54, Apr 58
Control tube in Westinghouse Chassis V-2233 . . . . 31, Mar 54
Critical circuit components . . . . . 9, Nov 55
Critical, General Electric Model 17T2 . . . . . 48, Feb 60
Isolating trouble . . . . . 24, Jan 59
Loss, RCA Chassis KCS117A . . . . . 60, Apr 60
Phase-inverter circuits . . 30, Mar 60
Servicing guide by symptoms . . . . . 17, May 56
Step-by-step troubleshooting procedure . . . . . 32, Sep 60
Waveform analysis . . . 28, Feb 60

SYNC SEPARATOR

Bias setter, General Electric ST line . . . . . 20, Oct 57
Plate-voltage analysis . . 28, Feb 60
Separate stages for horizontal and vertical sync . . . . . 20, Oct 57
Signal tracing . . . . . 25, Feb 56
Theory of operation . . . 15, Jul 52
Troubles . . . . . 54, Apr 58
6BU8 separator . . . . . 30, Mar 60 . . . . . 29, Jun 56
—waveforms . . . . . 44, Aug 59

TAPE RECORDERS

Adjustments to mechanism . . . . . 30, Jul 60
Ampex Model 600, circuits . . . . . 27, Oct 55
—transport mechanism . . . . . 13, Aug 55
Ampex Model 350 . . . . 21, Jul 54
Basic principles of operation . . . . . 18, Sep 57
Bias on heads . . . . . 19, Dec 54
Brakes . . . . . 18, Mar 56
Concertone Model 1502, transport mechanism . . . . . 5, May 55
Concertone Model 1401S . . . . . 29, May 54
Distortion on musical recordings . . . . . 72, Mar 60
Erase-circuit trouble . . . 54, Dec 60
Erase methods . . . . . 5, Feb 55
Frequency response of heads . . . . . 13, Mar 55
Frying sound in recordings . . . . . 72, Mar 60
Magnetized heads . . . . . 33, May 56
Maintenance . . . . . 33, May 56
—of tape speed . . . . . 16, Dec 55
Other types of magnetic recorders . . . . . 13, Nov 54
Reel squeak . . . . . 34, Jun 58
Servicing, essential points . . . . . 18, Sep 57
Tape-tension adjustments . . . . . 18, Mar 56
Transport mechanisms . . 5, Apr 55
—maintenance . . . . . 46, May 60
Weak playback of own recordings . . . . . 44, Aug 60
Wow and flutter . . . . . 16, Dec 55

TEST EQUIPMENT, MISC.

See also
Capacitor testers
Color-bar generators
CRT testers
Dot generators
Field-strength meters
Flyback testers
Oscilloscopes
Signal generators, audio
Signal generators, RF
Signal-substitution testers
Square-wave generators
Sweep generators
Test probes
Transistor testers
Tube testers

Voltmeters
VOM's
VTVM's
Wattmeters
Absorption analyzer
—Kingston Model EA-1 ..... 44, Aug 58
—Kingston Model VS4 ..... 36, Jul 57
AGC troubleshooter, Win-Tronix Model 825 ..... 23, Mar 57
Alternate names for instruments and controls ..... 5, Mar 53
Attenuators in instruments ..... 21, Apr 55
Attenuator pads ..... 5, Nov 52
Audio, general ..... 37, Oct 56 ..... 25, Feb 55
Audio tester, Win-Tronix Model 800 *Hi-Fi Stereo Analyzer* ..... 68 Feb 60
Audio VTVM, Arkay Model AV-20 ..... 64, Mar 60
Auxiliary high-voltage supply ..... 29, Sep 52
Base-line marker adapter, Hickok Model 691 ..... 6, Feb 54
Basic needs of service shop ..... 4, May 51
Battery tester, B & K Model 160 ..... 48, Sep 60
—Sencore Model BT-101 ..... 50, Jun 59
Calibration methods ..... 13, Sep 56
Calibrator, B & K Model 750 ..... 16, Jan 57
Cathode-current checker, Seco Model HC-6 ..... 46, Jan 59
Clamp-on ammeter adapter, Triplett Model 10 ..... 30, Aug 57
Coupling to circuit under test ..... 27, Feb 54
Crosshatch generator to check chroma phase ..... 44, Sep 59
Crystal calibrator, Win-Tronix Model 120 ..... 26, Jan 56
Electronic switch ..... 17, Dec 54
—B & M Model ES-40 ..... 48, Nov 58
Flying-spot scanner, B & K *Television Analyst* Model 1075 ..... 40, Jun 58
—B & K Model 1000 ..... 36, Jul 57
—Hickok *Video Scanner* ..... 42, Mar 58
Grid-dip meter, EICO Model 710 ..... 32, Jun 60
Hi-Fi Stereo Analyzer, Win-Tronix Model 800 ..... 68, Feb 60
Horizontal-sweep test unit, Doss *Pioneer 250* ..... 68, Nov 59
IF alignment setup ..... 16, Apr 58
Impedance-measuring device ..... 23, Jul 51
Induced-waveform analyzer, Winston Model 850 ..... 52, May 58
Industrial ..... 32, Mar 60
Interconnection diagrams ..... 13, Sep 55
Intermittent Condition Analyzer, Win-Tronix Model 828 ..... 30, Oct 57
Intermittent recorder, Magne-Pulse Type 202 ..... 17, Feb 54
Intermittent-trouble monitor, Seco SL-10 *Monitron* ..... 23, Sep 56
Intermodulation analyzer operation ..... 32, Apr 60 ..... 37, Oct 56 ..... 25, Feb 55
Limitations ..... 11, Feb 55
Line-current tester, Sencore *Fuse-Safe* ..... 22, Jun 58
Low-range ohmmeter, Simpson Model 362 ..... 36, Jul 57
Low-voltage measurements with current meters ..... 35, May 56
Marker adder, Hickok Model 691 ..... 15, Oct 54
—RCA Model WR-70A ..... 56, Oct 58
Marker calibrator, Hickok Model 690 ..... 19, Jan 55
Millivoltmeter, Simpson Model 387 ..... 30, Oct 57
Noise generator, Hickok Model 755 ..... 19, Jan 55
"Pic-probe" to produce TV picture on scope screen ..... 16, Jan 57
Radiation-measuring ..... 26, Dec 60
Radio-test unit construction project ..... 42, Jun 59
Rainbow generator, Win-Tronix Model 150 ..... 17, Aug 55
Selenium-rectifier tester, Century Model SRT-1 ..... 38, Sep 57
—Jackson Model 710 ..... 43, Jul 53
Semiconductor-rectifier substitution unit, Sencore Model RS106 ..... 76, May 60
Signal tracer, Precision Electronics Model 202 ..... 32, Jun 60
Static charges on meter windows ..... 15, Mar 54
Sweep-circuit tester
See Flyback Tester
Transformer and coil tester, Aerovox Model 97 ..... 60, Sep 58
—B & M Model 50-A ..... 36, Jul 57
Transistor-radio tester, Hickok Model 810 ..... 48, Apr 59
Trouble case histories ..... 63, Nov 55
Tube preheater, Sencore Model FP22 ..... 30, Aug 57
Types needed for shop ..... 19, Sep 54
Vibrator tester, EMC Model 906 ..... 30, Apr 58
Video-amplifier substitute, Simpson Model 406 ..... 25, Jul 55

TEST PROBES

Description of types ..... 31, Nov 53
Detector or demodulator probe ..... 14, Mar 58
—for alignment ..... 50, Nov 56
Doss *Hi-Leak Analyzer, Electrolytic Substitute*, and *Sync Master* ..... 60, Sep 58
Doss *Video Master* ..... 52, May 58
Kingston *Probe-Master* ..... 30, Jan 58
Low-capacitance ..... 28, Sep 59 ..... 28, Nov 58 ..... 20, Mar 56
—adjustments ..... 28, Nov 58
Selecting proper type for waveform checks ..... 28, Sep 59 ..... 14, Apr 58
Voltmeter probes, Futuramic ..... 30, Oct 57

THEORY

See
Circuit theory
Mathematics
Also under appropriate section of TV set (video IF, vertical sweep, etc.)

TOOLS

Drill bits for use on masonry ..... 12, Dec 55
General information ..... 40, Jan 58
Home-call stock ..... 14, Nov 56
Magnetizing or demagnetizing device, Perma-Power *Magneformer* ..... 22, Aug 58
Nonslip tool for adjusting rear controls ..... 40, Nov 56
Pliers and cutters ..... 34, Mar 58
Screw-holding screwdrivers ..... 30, Sep 56
Soldering gun, extension tips ..... 12, Nov 55
—special uses ..... 16, Dec 56
Soldering iron, temperature-controlled ..... 56, Feb 59
Wrenches ..... 34, Mar 58

TRANSFORMERS AND COILS

See also
Horizontal output transformers
Autotransformer substitution for vertical output transformer ..... 17, Feb 57
Focus coils, replacement of obsolete types ..... 17, Mar 56
Line-voltage adjustors ..... 17, Sep 55
Mounting adapter to save drilling new holes ..... 29, Jan 56
Phase relationship of primary and secondary voltages in double-tuned type ..... 23, Jan 56
Printed-wiring board mounting ..... 19, Feb 56
Stock of most popular types ..... 29, May 57

TRANSISTORS

See also
Transistor radios
Transistor testers
Transistor TV
Basic circuit configurations ..... 11, Apr 57
—for detector, amplifier, and oscillator ..... 5, Feb 54
Basic theory ..... 48, Nov 60 ..... 11, Sep 53
Biasing of elements ..... 48, Nov 60 ..... 30, Jul 59
Complementary PNP-NPN circuit ..... 11, Jun 57
Cross-reference chart of radio types ..... 30, Jul 59
DC-coupled amplifier circuits ..... 11, Jun 57
Diffused-junction type ..... 9, Feb 56
Electron flow through external circuit ..... 20, Aug 60
Frequency-response characteristics ..... 9, Jan 56
Glossary of terms ..... 121, Sep 53
Impedance matching to circuit ..... 11, Jul 57
Interchangeability problems ..... 22, Nov 58
Multistage circuits ..... 13, May 57
Open elements, effect on circuit voltages ..... 30, Jul 59
Output stages in auto radios ..... 13, May 57
Phase-inverter circuits ..... 11, Jun 57
Power types ..... 15, Mar 56
—failure in auto radios ..... 52, Nov 59
—in converter and inverter power supplies ..... 34, Feb 59
—replacement guide ..... 38, Mar 60
Resistance measurements ..... 46, Sep 58
Silicone grease for power-transistor mounts ..... 30, Oct 58
Specifications explained ..... 15 Apr 56
Testing ..... 30, Jul 59
TV applications ..... 13, Sep 57
Types other than conventional triodes ..... 17, Mar 54
Types used in earliest-model radios ..... 34, Jul 57 ..... 11, Jan 57
Voltage analysis of circuits ..... 20, Aug 60
Voltage relationships between elements ..... 30, Jul 59

TRANSISTOR RADIOS

Advanced troubleshooting techniques ..... 14, Aug 58
AGC circuits ..... 30, Jul 59 ..... 9, Aug 57
Alignment ..... 14, Aug 58
Auto type, Motorola GV-800 ..... 38, Sep 58
Battery drain, Motorola Model 56T1 ..... 52, Nov 59
Battery replacement ..... 20, Jul 58
Bench servicing ..... 16, Mar 57
Chassis removal from case ..... 20, Jul 58
Component replacement ..... 42, Oct 57
Locating components ..... 25, Jun 57
Low-voltage electrolytics, testing ..... 44, Mar 59
Miniature electrolytic capacitors ..... 16, Sep 56
Mitchell Model 1103 ..... 17, Jan 56
Raytheon Chassis 8RT1 ..... 25, Sep 55
Regency Model TR-1 ..... 13, Jan 55
Second-detector circuits ..... 11, Jul 57
Service case history ..... 42, Jun 57
Service hints ..... 25, Jan 57
Signal-tracing ..... 25, Jun 57
Static, Admiral Chassis 7L1 ..... 74, Aug 59
Test unit, Hickok Model 810 ..... 48, Apr 59
Troubleshooting chart ..... 11, Mar 55
Visual search for troubles ..... 42, Oct 57
Voltage and resistance measurements ..... 42, Oct 57

TRANSISTOR TESTERS

Basic test circuits ..... 24, Nov 60 ..... 9, Jun 56
B & K Model 160 ..... 48, Sep 60
Eby *Trans-Tester* ..... 30, Oct 57
EICO Model 666 ..... 16, Jan 57
General pointers for use ..... 30, Jul 59
Hickok Model 870 ..... 62, Oct 60
Hickok Model 850 *Transistor Analyzer* ..... 50, Apr 60
Incorporated in tube testers ..... 16, Jan 57
Motorola unit with audible indication ..... 60, Nov 60
Precision Apparatus Model 660 ..... 38, Nov 57
Radio City Products Model 325 ..... 23, Sep 56
Seco Model 100 ..... 68, Sep 59
Sencore Model TRC4 ..... 30, Apr 58
Sencore Model TDC22 ..... 38, Sep 57
Triplett Model 690 ..... 44, Aug 58

TRANSISTOR TV

General Electric experimental 8" set ..... 28, Jan 59
Sync circuits ..... 10, Oct 57
Texas Instruments experimental set ..... 18, Nov 58
Troubleshooting ..... 20, Jan 59
Tuner for Motorola 19" *Astronaut* ..... 36, Sep 60
Vertical sweep circuits ..... 12, Nov 57

TUBES

See also
Damper
Tube Stock Guide
Tube testers
Characteristic curves explained ..... 12, Jan 58 ..... 12, Dec 57
Characteristics rp, Gm, mu ..... 11, Apr 54
European types widely imported ..... 32, Sep 58
Frame-grid construction ..... 26, Mar 60
Grid emission and gas ..... 27, Aug 55
Hi-fi types most popular ..... 34, Oct 58
Horizontal output ..... 9, Apr 56
—damage due to retaining clip in General Electric Model 21C225 ..... 76, Sep 59
—tube current and voltage chart ..... 32, Feb 59

Hybrid auto types ....36, Feb 59
IF pentodes in recent TV sets
.....30, Jan 59
New types .....26, Mar 60
Nuvistors .....28, May 59
—RF amplifier, 6CW4 .36, Sep 60
Portable-radio 1-volt types, frequent failure ....32, May 58
Radio and hi-fi types in widest use
.....34, Jul 60
Rare types used in TV sets
.....30, Jun 59
Red glow on plates ...34, Aug 60
Replacement, effect on circuit operation .....26, Apr 60
Ruggedized horizontal-output type
.....7, Mar 54
Series-parallel heater hook-up in Motorola sets .....24, Oct 57
Series-string, checking for open heater .....23, May 55
—tube failure .....25, Apr 57
—300-ma, in General Electric 9" TV .....27, Mar 57
—600-ma types .....9, Apr 56
.....21, Sep 54
Shields, captive .....29, Jun 56
Shortened life, case histories
.....54, Sep 59
Stock inventory .....4, Mar 52
Stock for radio servicing
.....17, Jul 56
Substitution Guide ....46, Oct 60
.....22, Jun 58
.....9, Aug 56
Testing in home—when to test and when to substitute ..46, Oct 59
Tetrode RF amplifiers .26, Mar 60
Triode-pentodes, comparison of types .....34, Jun 57
Types of failures .....7, Nov 52
UHF .....47, Jan 53
Vertical output types, 110°
.....30, Jun 59
2V2, specifications ....5, Oct 54
5AU4, specifications ...5, Oct 54
5U4GA, specifications ..5, Oct 54
6BQ6GA, specifications .5, Oct 54
6BU8, operation .....18, Apr 58
.....29 Jun 56
6CA5, 12CA5, specifications
.....27, Feb 55
6CM7, specifications ...9, Oct 55
6CU6, characteristics ..19, Feb 54
6DT6, operating principles
.....19, Dec 56
6ER5, structure .....26, Mar 60
6SN7GTA-B .....9, Apr 56
12BY7 burnout, Westinghouse Chassis V-2342 ....21, Jun 59

TUBE STOCK GUIDE

—41, May 53
—123, Jul 53
—124, Sep 53
—117, Nov 53
—61, Feb 54
—63, Apr 54
—71, Jun 54
—59, Aug 54
—61, Oct 54
—67, Dec 54
—71, Feb 55
—55, Apr 55
—65, Jun 55
—63, Aug 55
—41, Oct 55
—26, Dec 55
—47, Feb 56
—39, Apr 56
—27, Jun 56
—45, Aug 56
—35, Oct 56
—50, Dec 56
—29, Mar 57
—55, Jun 57
—60, Sep 57
—47, Jan 58
—38, Apr 58
—44, Oct 58
—58, Apr 59
—42, Oct 59
—38, Apr 60
—42, Oct 60

TUBE TESTERS

Basic principles .....27, Nov 56
B & K Model 650 *Dyna-Quik*
.....42, Mar 58
Combined with VTVM, Hickok *Caddy Pal* Model 820
.....64, Mar 60
EICO Model 666 ....16, Jan 57
Gas test, Triplett Model 3423
.....27, Aug 55
Hickok Model 6000 ..46, Jul 59
Hickok *Cardmatic* Model 121
.....44, Aug 58
.....23, Mar 57
Jackson Model 658 ....60, Jan 60
Jackson Model 648R ..68, Nov 59
Jackson Model 49 ....13, May 56
Leakage checker, Sencore Model LC2 .....27, Nov 56
Mercury Model 300 *Combination Tester* .....36, Dec 60
Multiple-socket type ..11, Sep 55
Precision Apparatus *Electronamic* Model 10-40 .....48, Apr 59
Precision Apparatus Model 660
.....38, Nov 57
Radio City Products Model 325
.....23, Sep 56
RCA Model WT-110A, card-operated .....38, May 59
Roll charts for Precision models
.....16, Apr 56
Seco Model 78 .....68, Feb 60
Seco Model 107 portable
.....38, Sep 57
Seco Model GCT-1 ...17, Dec 54
Sencore *Mighty Mite* Model TC109
.....60, Nov 60
Shell Model TC-18 *Cadi-Tester*
.....62, Oct 60
Shell Model P-18 *Test-O-Matic*
.....50, Jun 59
Shorts tests—general hints
.....19, Jan 55
Simpson Model 1000 ..15, Mar 54
Time-saving units ....11, Sep 55
Triplett Model 3444 ..50, Apr 60
Triplett Model 3414 ..50, Mar 59
Triplett Model 3423 ...6, Feb 54
—gas test .....27, Aug 55
—late production changes
.....17, Aug 55
—testing selenium rectifiers
.....31, Apr 54
Vis-U-All Model V1003
.....52, Dec 59
Vis-U-All Model V1001
.....60, Sep 58

TUNERS, FM AND AM-FM

AFC circuits .....20, Jul 59
.....25, Jul 56
Alignment .....16, Aug 57
Auto radio, Lincoln Model 88BH
.....40, Jul 58
Dual-channel AM-FM, Madison Fielding Series 330 ..22, Nov 58
FM signal theory ....18, Jul 58
Hoffman Chassis 1110 .40, Apr 58
Multiplex, basic principles
.....18, Jul 58
National *Criterion* ....27, May 55
RF subchassis .....28, Nov 60
Regency *Tele-Verter* ..44, Dec 57
Servicing .....29, Jan 55
Signal-tracing with AM generator
.....18, May 59
—with scope .....19, Sep 53
Specifications defined ...5, Jul 55
Sweep generator for servicing
.....32, May 58
Table radios .....28, Nov 60
Weak sensitivity in FM section
.....56, Jun 60

TUNERS, TV

Adjacent- and co-channel interference .....34, May 57
Alignment setup .....28, Jul 59
.....60, Nov 57
.....11, Oct 54
Antenna and RF input circuits
.....12, Aug 57
Automatic fine tuning, Westinghouse Chassis V-2372
.....44, Feb 58
Balun melted .....26, Sep 57
Cascode circuit .....52, Sep 57
—burned resistor in RF stage
.....60, Jun 60
Channel-frequency table
.....9, Sep 56
Continuous type, Raytheon Model M1611 .....44, Dec 58
Determining whether alignment is needed .....28, Jul 59
Dismantling, switch type
.....20, Nov 58
—turret type .....16, Sep 57
Electrical defects, general
.....5, Aug 54
Filter circuits .....4, Mar 52
Fine-tuning, drive-cord restringing in Motorola Chassis TS-552
.....26, Jun 59
—push-button "do-it-yourself"
.....38, Sep 58
General Instrument Model 44
.....13, Mar 51
—Model 45 .....5, Jan 51
Hallicrafters printed-circuit type
.....13, Mar 51
Increasing sensitivity ...5, Sep 54
Intermittent oscillation in *Neutrode* tuners .....60, Dec 59
Lightning damage ....25, Aug 55
.....41, Sep 53
Mechanical troubles ...42, Jun 60
.....5, Aug 54
Motorized tuning mechanisms
.....30, Dec 60
.....28, May 59
.....12, Feb 57
—Philco Chassis TV-394
.....25, May 56
Neutrode circuit .....52, Sep 57
Nuvistor types .....36, Sep 60
One-tube type, trouble in
.....17, Apr 55
Oscillator adjustment, affecting all channels .....20, Mar 58
—in switch-type tuner .56, Oct 57
Oscillator-mixer circuit operation
.....60, Oct 57
Oscillator-tracking difficulty, Magnavox Chassis CTA427CE
.....70, Oct 58
Poor reception on Channel 12 only
.....70, Oct 58
Precautions in component replacement .....23, Oct 55
RF amplifier tube, repeated failures due to AGC fault ...42, Sep 60
RF input circuit defective, Arvin Chassis TE-341 ...50, Feb 59
RF stage design .....52, Sep 57
Replacement of original in Crosley Model 11-446 .....24, Feb 58
Response check .....28, Mar 59
.....42, Mar 58
Sarkes Tarzian, *Hot Rod*
.....26, Mar 59
—*Silver Sealed* .....36, Sep 60
—Model TT-3 .....5, Jan 51
Service case histories ..46, Jan 59
Service hints .....15, Mar 55
Servicing guide by symptoms
.....11, Jul 55
Short to earth ground through tuner .....26, Sep 57
Signal-injection testing .22, Sep 58
Signal tracing .....14, Mar 58
Snowy picture due to defective AGC delay circuit ..46, Jun 59
Standard Coil, *Fireball*
.....26, Mar 60
—*Guided Grid* .....24, Oct 57
—older models .....5, Jan 51
—T series .....15, Aug 55
—T series, UHF versions
.....25, Apr 56
—TC-009, voltage requirements
.....58, Nov 58
Step-by-step troubleshooting procedure .....24, Jul 60
Stray capacitance and inductance
.....58, Oct 59
Tetrode circuit .....52, Sep 57
Theory of operation, general
.....5, Jan 51
Transistorized, for Motorola *Astronaut* set .....36, Sep 60
Trimmer capacitor broken
.....21, Apr 56
Zenith switch type ....17, Jul 55

TURNTABLES

Rek-O-Kut Model LP-743
.....7, May 54
Rumble cures .....30, Apr 57
Speed problems .....48, Dec 60

UHF CONVERTERS AND TUNERS

See also
UHF field surveys
UHF television
Arvin all-channel tuning
.....23, Nov 52
Astatic Model UHF ...21, Oct 54
—Model CB-1 .....27, Nov 53
Blonder-Tongue Model BTU-1
.....29, Sep 53
—Model BTU-2B ....29, Feb 55
—Model 99 .....21, Nov 54
Bogen Model UCT ....29, Sep 53
Cardwell Model ES-1 ..21, Oct 54
Crosley *Ultratuner* .....7, Jan 52
DuMont .....7, Jan 52
Fen-Tone Model C1 ..21, Nov 54
General design trends ..59, Jan 53
General Electric Model UHF-101
.....7, Jan 52
—Model UHF-103 ...23, May 53
General Instrument (Silverline) Model 63A .....27, Nov 53
Granco Model CTU ..29, Sep 53
—Model LCU and *Hide-Away*
.....15, Apr 54
—Model SLU .....29, Feb 55
—Models UH-1, UJ-5
.....21, Feb 54
ITI Model IT-150R ..29, Feb 55
Mallory Model TV-101
.....23, Nov 52
Motorola, kit installation
.....39, Mar 53
—Models TC-101, TK-17M
.....35, Jan 53
Operating characteristics
.....31, Mar 53
Philco types .....23, May 53
RCA Models U1A, U1B, U2
.....35, Jan 53
RME Model 200 .....15, Jul 53
Raytheon Model UHF-100
.....23, Sep 52
Recent service information
.....20, Dec 57
Regency Model RC53 ..21, Nov 54
—Model RC600 ....23, Nov 51
Servicing, general .....5, Nov 54
.....5, May 54
Standard Coil, strips for single-channel reception ...37, Sep 53
.....35, Mar 53
—T Series .....25, Apr 56
—82-channel tuner ....5, Nov 54
.....23, May 52
Stromberg-Carlson .....7, Jan 52
Sutco Model 37A ....21, Feb 54
Sylvania Model C31M ..23, Sep 52
—Model C33M .....15, Jul 53
Test equipment .....11, Aug 54
Turner Model TV-3 ..27, Nov 53

Walsco Model 2000 . . 21, Feb 54
Westinghouse types . . . . 15, Jul 53

UHF FIELD SURVEYS

Anderson, Ind. . . . . 23, Mar 54
Baton Rouge, La. . . . . 29, Jul 53
Fort Wayne, Ind. . . . . 14, Sep. 56
Jackson Miss. . . . . 29, Jul 53
Mobile, Ala. . . . . 29, Jul 53
Norfolk, Va. . . . . 11, Nov 53
Reading, Pa. . . . . 43 May 53
South Bend, Ind. . . . . 9, Mar 53

UHF TELEVISION

Antennas . . . . . 21, Mar 53
. . . . . 25, Jan 53
Channel-frequency table
. . . . . 9, Sep 56
Converter circuitry, general
. . . . . 7, Jan 52
Deintermixture plans of FCC
. . . . . 13, Oct 56
Experiments—Bridgeport, Conn.
. . . . . 4, Jul 51
Glossary of terms . . . . 45, Jan 53
Lead-in . . . . . 27, Mar 53
—inductive effects . . . . . 5, Jul 53
Test equipment . . . . . 27, Nov 54
. . . . . 6, Feb 54
. . . . . 9, Jan 53
Tubes for tuners . . . . . 47, Jan 53
Twin-lead characteristics
. . . . . 5, Jan 53
. . . . . 33, Jan 53

VERTICAL-RETRACE BLANKING

Installation . . . . . 10, Aug 58
. . . . . 17, May 54
—Fada Model 21L1 . . 74, Aug 59
—RCA Chassis KCS72
. . . . . 48, Feb 60
—Sparton Model 26SD170
. . . . . 82, May 60
Typical circuits . . . . . 9, Sep 51

VERTICAL SWEEP

Autotransformer substitution for isolated-secondary output transformer . . . . . 17, Feb 57
Blocking oscillator, cathode-grid type . . . . . 18, Jan 58
—theory . . . . . 51, Jan 53
—troubleshooting . . . . . 50, Jun 58
Burned output-plate resistor due to removing oscillator tube
. . . . . 60, Apr 59
Component failures, specific cases
. . . . . 50, Jun 58
Critical circuit components
. . . . . 9, Nov 55
Compressed lines in band near mid-raster . . . . . 82, May 60
. . . . . 18, Jan 58
Distortion due to "knee" in tube characteristic curve . . 18, Jan 58
Distortion due to video "crosstalk" in sweep . . . . . 48, Sep 59
Feedback-capacitor failure, Emerson Chassis 120220D
. . . . . 68, Sep 60
Foldover . . . . . 35, Apr 55
—Admiral Chassis 21F1
. . . . . 60, Apr 59
—Emerson Chassis 120133B
. . . . . 58, Nov 58
—severe, in Hoffman Chassis 211
. . . . . 60, Jul 59
Height insufficient . . . . 40, Aug 59
—Admiral Chassis 20Y4E
. . . . . 44, Mar 59
—due to low boost . . . 39, Feb 57
Height lacking, General Electric Model 21C201 . . . . 22, Apr 58
Intermittent collapse, Motorola Chassis TS-74 . . . . . 44, Aug 60
Intermittent troubles . . 40, Aug 59
Keystone effect, RCA Chassis KCS49A . . . . . 76, Nov 60
Linearity . . . . . 40, Aug 59
. . . . . 35, Apr 55
. . . . . 25, Apr 54
—adjustment . . . . . 26, Apr 60
—troubles, Emerson Chassis 120123B . . . . . 38, Oct 59
Multivibrator with linearity control in output-tube grid circuit
. . . . . 60, Apr 59
Multivibrator combined with output stage, theory of operation
. . . . . 18, Jul 57
. . . . . 15, May 53
Muntz Model 621C circuit operation . . . . . 84, May 60
No sweep, General Electric Model 14C102 . . . . . 24, Feb 58
—except when tuned to station
. . . . . 54, Jul 60
Output-stage troubleshooting
. . . . . 50, Jun 58
Output tube has insufficient bias, Crosley Chassis 385 . 44, Mar 59
Servicing guide by symptoms
. . . . . 50, Jun 58
. . . . . 17, Jun 56
Step-by-step troubleshooting procedures . . . . . 38, Jan 60
Troubleshooting . . . . . 16, Jun 57
—with boost disabled . . 54 Oct 60
Two stacked pictures . . 48, Sep 57

VERTICAL SYNC

Bounce, Trav-Ler Model 1722
. . . . . 44, Aug 60
Critical, Magnavox 250 Series
. . . . . 52, Nov 59
Drift of oscillator frequency, General Electric Model 21C113
. . . . . 26, Jul 58
Equalizing pulses and serrations
. . . . . 74, Aug 59
Interaction with horizontal sync, Philco Model A-T1818
. . . . . 20, Mar 58
—due to AGC trouble, Silvertone Model 5160 . . . . . 60, Apr 59
Integrator action . . . . 34, Apr 60
. . . . . 51, Jan 53
Interlace problems . . . . 32, Jan 60
. . . . . 48, Sep 59
Jitter . . . . . 34, Apr 60
. . . . . 48, Sep 59
—Admiral Chassis 22P2
. . . . . 22, Apr 58
—Crosley Chassis 431-3
. . . . . 54, Jul 60
Rolling—
—back and forth, caused by wrong setting of fringe switch, Emerson Chassis 120169B . . . 26, Jul 58
—General Electric "K" line
. . . . . 60, May 58
—hints for troubleshooting
. . . . . 72, Mar 60
—intermittent . . . . . 13, Dec 56
—intermittent, Zenith Model R2671E . . . . . 62, May 58
—Olympic Chassis DD
. . . . . 76, Sep 59
—Philco Chassis TV-301
. . . . . 70, Oct 60
—Zenith Model Z2223R
. . . . . 54, Jul 60
Unstable, General Electric Model 21C238 . . . . . 60, May 58

VIBRATORS

Noisy when car is accelerated
. . . . . 60, May 58
Tester, EMC Model 906
. . . . . 30, Apr 58
Theory of operation . . 43, Sep 52

VIDEO AMPLIFIERS

Contrast and brightness troubles, general . . . . . 26, Oct 59
Contrast poor, Motorola Model 17T22 . . . . . 60, Dec 59
—Stromberg-Carlson Model 21TM
. . . . . 74, Aug 59
Direct-coupled type . . . . 7, Mar 52
Frequency response, adjustment in RCA Model 27D384
. . . . . 29, Jan 54
—check with generator and scope
. . . . . 36, Dec 58
. . . . . 27, Jan 54
—control, Sentinel *Hi-Lite*
. . . . . 39, Nov 53
Negative picture . . . . . 30, Oct 60
—Emerson Model 1114J
. . . . . 48, Nov 58
Oscillations producing vertical-bar symptom, Raytheon Model M1712 . . . . . 42, Jan 60
Ringing (transients) . . 15, Nov 51
Servicing guide by symptoms
. . . . . 17, Nov 55
Smear in picture, varying with volume setting, Philco Model 18B3002 . . . . . 72, Mar 60
Sound bars in RCA Chassis KCS47
. . . . . 48, Feb 60
Sound traps . . . . . 7, Mar 52
Step-by-step troubleshooting procedure . . . . . 38, Jan 60
Theory of operation . . 10, Aug 56
. . . . . 5, Sep 51
Tube burnout, Westinghouse Chassis V-2342 . . . . 21, Jun 59
Westinghouse two-stage circuit
. . . . . 19, Apr 57

VIDEO DETECTOR

Germanium diode servicing
. . . . . 25, Apr 54
. . . . . 4, Mar 52
Servicing guide by symptoms
. . . . . 17, Oct 55
. . . . . 29, Sep 55
Theory of operation . . . . 5, Sep 51
Troubleshooting . . . . . 25, Jun 54

VIDEO IF

Alignment hints . . . . . 18, Dec 58
Alignment setups . . . . 16, Apr 58
Bifilar-wound interstage transformers . . . . . 23, Apr 57
Components damaged by prolonged operation with AGC shorted to boost . . . . . 38, Aug 57
Coupling circuits . . . . . 23, Apr 57
Ghosts due to IF defect
. . . . . 56, Jun 60
Grid blocking, Emerson Model 1155 . . . . . 24, Feb 58
Hum entering through heater or AGC . . . . . 33, May 52
Increased signal-handling capacity
. . . . . 5, Aug 55
Intermittent regeneration, Stromberg-Carlson Chassis 622
. . . . . 60, Apr 60
Interstage coupling circuits
. . . . . 30, Nov 59
Miller effect . . . . . 56, Jun 60
. . . . . 30, Nov 59
. . . . . 58, Oct 59
Precautions in component replacement . . . . . 23, Oct 55
Regeneration . . . . . 28, Dec 60
. . . . . 12, Feb 58
. . . . . 15, Nov 51
Rejection ratio . . . . . 5, Jun 55
Response curve explained
. . . . . 30, Nov 59
—RCA Chassis KCS47B
. . . . . 60, Dec 59
Servicing guide by symptoms
. . . . . 29, Sep 55
. . . . . 17, Oct 55
Signal tracing . . . . . 14, Mar 58
Single-stage, Olympic Chassis DY
. . . . . 22, May 58
Step-by-step troubleshooting procedure . . . . . 24, Jul 60
Stray capacitance and inductance
. . . . . 48, Oct 59
Theory of operation . . . 5, May 51
Trap circuits . . . . . 30, Nov 59
Tubes defective in three out of four stages . . . . . 25, Jan 57

VIDEO SPEED SERVICING

Admiral Chassis 16AX1, 16X1
. . . . . Feb 60
—Chassis 17AC1 . . . . . Jan 59
—Chassis 17AC1 . . . . . Mar 60
—Chassis 20B6C . . . . . Sep 59
—Chassis 20S6 . . . . . Oct 60
Airline Chassis GTM-4213A
. . . . . Jun 60
—Model WG4204A, Serial 85X
. . . . . Nov 58
Andrea Chassis VR121 . . . Oct 59
DuMont Chassis RA-400/-401
. . . . . Apr 59
—Chassis RA-402, -403
. . . . . Oct 58
Emerson Chassis 120341H, 120342R, 120358H, 120359R
. . . . . Sep 58
—Chassis 120407S . . . . . Nov 59
General Electric Chassis M3
. . . . . Sep 58
—Chassis M4 . . . . . Dec 59
—Chassis Q2 . . . . . Mar 59
—Chassis U4 . . . . . Dec 60
Hoffman Chassis 426 . . . . . Oct 60
Magnavox Chassis 24 Series
. . . . . Oct 59
—Chassis 25 Series . . . . . Dec 59
—Chassis 26 Series . . . . . Aug 59
—Chassis 30 Series . . . . . Apr 60
Motorola Chassis TS-542 . . Dec 58
—Chassis TS-558 . . . . . Jul 60
—Chassis TS-561 . . . . . Jun 60
—Chassis TS-564 . . . . . Sep 60
Olympic Chassis JA . . . . Nov 60
Packard-Bell Chassis 88S4, 88S3
. . . . . Oct 58
Philco Chassis 7E10 . . . . . Apr 59
—Chassis 7L40 . . . . . Jul 59
—Chassis 7L70 . . . . . Sep 59
—Chassis 9H25 . . . . . Jan 60
RCA Chassis KCS108 . . . . Jun 59
—Chassis KCS108 C,D,E,F, etc.
. . . . . Nov 58
—Chassis KCS116B . . . . . Jan 60
—Chassis KCS120A,B . . . Nov 59
—Chassis KCS121K . . . . . Jan 59
—Chassis KCS122A,-B . . Mar 59
—Chassis KCS122BA . . . Mar 60
Setchell-Carlson Chassis 259
. . . . . Jul 60
Silvertone Chassis 528.51580
. . . . . May 60
Sylvania Chassis 1-532-3 . . Feb 60
—Chassis 1-537-1 . . . . . Dec 58
—Chassis 1-537-5 . . . . . Jul 59
—Chassis 1-541-7 . . . . . May 60
—Chassis 1-542-1 . . . . . May 59
—Chassis 1-544-1 . . . . . Sep 60
Trav-Ler Chassis 1150-19 . Aug 60
Westinghouse Chassis V-2340,-50
. . . . . Feb 59
—Chassis V-2366-1 . . . . . Apr 60
—Chassis V-2372, V-2382
. . . . . May 59
—Chassis V-2384-1 . . . . . Nov 60
Zenith Chassis 15B20,Q . . . Jun 59
—Chassis 16D21 . . . . . Aug 60
—Chassis 18E20 . . . . . Dec 60
—Chassis 19A30,-Q . . . . . Feb 59
—Chassis 19B20,Q . . . . . Aug 59

VOLTMETERS, GENERAL

Input impedance . . . . . 15, Jul 54
Special applications . . . 28, Oct 59
Tolerances permissible in readings . . . . . 32, Oct 56
VOM-VTVM combination, Triplett Model 631 . . . . . 13, Jun 54

VOM's

Adapters for adding to Simpson Model 260 or 270 . . 60, Jan 60
Arkay Model MT-50 *Multi-Tester*
. . . . . 76, May 60
EMC Model 109 . . . . . 48, Jul 60
Hickok Model 470 . . . 70, Oct 59
Hickok Model 457 . . . 38, May 59
Mercury Model 300 *Combination Tester* . . . . . 36, Dec 60
Phasotron Model 555 . . 21, Apr 55
Precision Apparatus Model 120

.....15, Jun 55
—Model 120M .....30, Apr 58
RCA Model WV-38A .50, Apr 60
Simpson Model 270 ..68, Nov 59
—Model 260, Series III
.....42, Mar 58
—Model 355 *Midgetester*
.....19, Mar 55
—Model 269 .....6, Feb 54
Specifications of service types
.....26, Jan 56
Triplett Model 310 ....24, Oct 55
—Model 630-PL .....36, Oct 58
—Model 630-NA .....25, Jul 55
Use on hot-chassis receiver
.....34, Jun 58

VTVM's

Adjustments .....46, Apr 57
Anchor Model V500, batteryless type .....38, Sep 57
Arkay Model AV-20, audio type
.....64, Mar 60
—Model VT-10 .....68, Sep 59
Checking accuracy using instrument's own meter
.....35, May 56
Checking capacitors for leakage
.....30, Jul 58
Circuitry .....46, Apr 57
Combined with tube tester, Hickok *Caddy Pal* Model 820
.....64, Mar 60
EICO Model 232 ....13, May 56
Hickok Model 225 ...15, Mar 54
Hycon Model 614 ....19, Sep 55
Jackson Model 590 ...46, Jul 59
Peak-to-peak AC measurements
.....15, Jul 54
Precision Apparatus Models 68, 78
.....28, Jul 56
—Model 88 .....15, Jun 55
RCA Kit Model WV-77E
.....52, Aug 59
—Model WV-77C ....48, Dec 58
Seco Model 208 .....70, Feb 59
Simpson Model 715, AC type
.....48, Sep 60
—Model 311 .....48, Nov 58
Specifications of service types
.....16, Apr 56
Sylvania Type 301-2 *Polymeter*
.....19, Jan 55
Tube replacement ....46, Apr 57

WATTMETERS

Power factor compensation
.....23, Nov 55
Sencore *Fuse-Safe* Model FS-3
.....22, Jun 58
Triplett *Load-Chek* ...25, Mar 52

WAVEFORMS

Amplitude measurement
.....32, Dec 57
Basic principles of analyzing
.....15, Jan 52
Cathode signal of horizontal-AFC reactance tube in Gruen system
.....60, May 58
Circular, notched patterns in color TV work .....17, Aug 55
Color TV circuits .....7, Nov 54
Distortion due to faulty test hook-up .....34, Apr 60
Effect of scope's frequency response on waveshape .....14, Apr 58
.....52, Mar 58
Equalizing pulses and serrations
.....74, Aug 59
Flyback circuit .....27, Apr 56
.....11, Mar 54
High-voltage circuit ..17, May 55
Horizontal AFC, dual-diode
.....22, May 54
—Gruen type .....36, Jul 59
.....31, Sep 54
—newest pulse-width circuit
.....34, Nov 59
—pulse-width type ....36, Jul 58
—reactance-tube type .23, Aug 54
—recent Motorola reactance-tube type .....28, Jul 60
—triode type .....23, Sep 55
Horizontal blocking oscillator, *Synchroguide* .....15, Jun 54
Horizontal multivibrator
.....62, Oct 58
.....22, May 54
.....33, Nov 52
Horizontal oscillator, sine-wave
.....31, Sep 54
—recent Motorola type
.....28, Jul 60
—recent Zenith type ...36, Jul 59
Horizontal output and damper
.....27, Apr 56
.....11, Mar 54
IF alignment response curves
.....16, Apr 58
Improvement when special probes are used .....28, Sep 59
Integrator circuit .....34, Apr 60
Interpreting meaning ..13, Dec 54
Key test-point .....14, Jan 58
Lissajous patterns .....14, Oct 56
Low-voltage (B+) power supply
.....36, Jan 59
Negative picture .....30, Oct 60
Polarity .....5, Apr 54
Secondary test points in TV
.....30, Nov 60
Square-wave test of video amplifier
.....36, Dec 58
.....25, Feb 55
Sync section .....28, Feb 60
—normal and abnormal
.....32, Sep 60
—phase inverter .....30, Mar 60
—separator, 6BU8 ...44, Aug 59
Tuner response curves .60, Nov 57
Vertical sweep .....13, Mar 52
—blocking oscillator ..18, Jan 58
Video and sync, pointing out details
.....14, Jul 57
Video IF, using detector probe
.....29, May 52
Video sweep in color receiver
.....13, May 55
Yoke current .....52, Mar 58
.....23, Jan 54

YOKES

Arcing, internal .....29, Jan 56
Damping .....44, May 58
Design features .....5, Mar 55
Effect on high voltage when disconnected .....22, Apr 58
Lining to prevent width-sleeve short
.....56, Oct 57
Loosening when stuck to CRT neck
.....74, Aug 59
Replacement hints ....44, May 58
Replacement types for Packard-Bell Model 2114 .....56, Jun 60
Service hints .....5, Mar 55
Shielded, Sylvania Chassis 1-533-7
.....19, Feb 57
Symptoms of trouble ..26, May 59
90° to replace 70° ...72, Mar 60

SUPPLEMENTARY INDEX TO MAJOR ARTICLES

Since the preceding main index section does not include article titles, this supplementary index has been prepared to further guide you in locating the information you're looking for.

In addition to the articles, PF REPORTER contains many regular columns and departments, most of which are detailed in the main Index. Thumbnail sketches of these departments follow:

ACROSS THE BENCH—A departmental feature which has appeared bimonthly since June, 1958 to the present. Mainly discusses restoration techniques for the more durable models of older TV receivers, including pertinent points of troubleshooting.

AUDIO FACTS—A regular column since November, 1951, now appearing bimonthly. Earlier subjects concentrated on hi-fi components, including some construction projects; later articles emphasized troubleshooting and testing all types of audio and hi-fi systems.

DOLLAR AND SENSE SERVICING—A regular department since the very first issue, containing thought-provoking items on business, sales, and related topics.

NOTES ON TEST EQUIPMENT—Since February, 1955, has analyzed the specifications and applications of test instruments designed for electronic servicing.

PRODUCT REPORT—A monthly feature since February, 1956, giving condensed descriptions of new products available to servicemen.

PREVIEWS OF NEW SETS—A monthly pictorial feature since September, 1958, pointing out design features of the newest TV receivers.

QUICKER SERVICING—Began in November, 1951, appearing in every issue to the present. Topics discussed include servicing short cuts, case histories of unusual troubles, various troubleshooting suggestions, and reviews of products which help servicemen increase their efficiency.

SERVICING INDUSTRIAL ELECTRONICS—Beginning in September, 1957 as a basic coverage of various industrial electronic systems, this column has become a regular bimonthly department. Its purpose is to provide servicemen with the background knowledge needed to service all types of industrial equipment.

SERVICING NEW DESIGNS—First appeared in November, 1951, as "Examining Design Features"; now a regular bimonthly department. Subject matter is focused on circuit-operating theory combined with servicing hints; another frequent topic is unusual chassis design, usually in the TV field but occasionally dealing with radio or audio.

SHOP TALK—A monthly feature from the first issue until May, 1958; since then a bimonthly department. Its popularity stems from down-to-earth discussions of basic troubleshooting techniques, transistor theory and circuit design, test-equipment applications, antenna design, and similar subjects.

STOCK GUIDE FOR TV TUBES—Since July, 1953, has appeared from two to six times yearly

to give servicemen information on relative usage of different TV tube types. Recent issues have included a listing of a recommendeo caddy stock of 350 tubes for home calls.

THE TROUBLESHOOTER—"The serviceman's Ann Landers"—began in December, 1957, to answer readers' specific questions on service problems. Most of these items are listed under the appropriate headings in the main index.

TROUBLESHOOTING WITH GEORGE—This series of features ran frequently in the period from November, 1956 to September, 1958, giving case histories of odd and difficult TV troubles.

UHF (Circuits and Equipment for Ultra-High-Frequency Reception)—Appeared in most issues between May, 1952, and April, 1954, presenting data on UHF converters and tuners of the early post-freeze era.

VIDEO SPEED SERVICING—Since September, 1958, this department has passed along service hints based on actual field experiences with specific models of TV receivers.

ANTENNAS

Components for Master Antenna Systems ..... Aug 60
Let's Talk Antennas ..... Jul 60
Understanding Antenna Rotators ..... Jun 60
Line-Cord TV Antennas ..... May 60
Selling TV Distribution Systems ..... Mar 60
Homeowners' TV Antenna Handbook ..... Feb 59
Setting Up a Tower ..... Sep 58
What Do You Know About Indoor Antennas? ..... Mar 58
Go Modern in Auto Antenna Installations ..... Jun 57
Checking Outdoor Antenna Installations ..... Apr 57
Within the Antenna (TACO) delay line) ..... Aug 56
Maintenance of Antenna Towers Aug 56
Antenna Troubles ..... Jul 56
Basc Mounts for Antenna Masts May 56
Antenna Insurance ..... Feb 56
Interference Rejection ..... Jan 56
Polar Graphs ..... Dec 55
Codes and Regulations for Antenna Installations ..... Nov 55
Antennas—The Eyes of TV Receivers ..... Sep 55
Rotator Repair ..... Dec 54
Antenna Principles (2 parts) ..... Apr, Aug 54
TV Rhombic Design ..... Feb 54
Guying Chart ..... Jan 54
A Multiple Antenna Switching Device ..... Jul 53
UHF Lead-Ins ..... Mar 53
Which Antenna for UHF? ..... Mar 53
UHF Transmission Lines and Accessories ..... Jan 53
UHF Antennas ..... Jan 53

AUDIO

Regular Recorder-Repair Routines ..... Jul 60
Care of Tape-Transport Mechanisms ..... May 60
A Review of Intercom Systems .. May 60
Choosing PA Amplifiers ..... Nov 59
Understanding Sound Systems ... Jan 59
Portable Sound Systems ..... Nov 58
Hints on Record-Changer Servicing (part 2) ..... Sep 58
Converting to Stereo-Disc Reproduction ..... Jul 58
Phono-Cartridge Replacement ... Jun 58
Hints on Record-Changer Servicing (part 1) ..... May 58
Essentials of Tape-Recorder Servicing ..... Sep 57
Curing Turntable Rumble ..... Apr 57
Maintenance of Tape Recorders May 56
Record-Changer Adjustments (2 parts) ..... Apr, May 56
Installing Home Intercom Systems ..... Apr 56
Brakes and Tape Tension ..... Mar 56
Maintenance of Tape Speed .... Dec 55
Circuits in the Ampex Model 600 Tape Recorder ..... Oct 55
Transport Mechanism in the Ampex Model 600 ..... Aug 55
Transport Mechanism in the Concertone Model 1502 ..... May 55
Tape-Transport Mechanisms .... Apr 55
Frequency Response in Magnetic Recording ..... Mar 55
Erase Methods in Magnetic Recorders ..... Feb 55
Bias for Magnetic Recording .... Dec 54
Magnetic Recording ..... Nov 54
The Ampex Tape Recorder Model 350 ..... Jul 54
The Concertone Tape Recorder.. May 54
The Williamson Amplifier—A Modified Design ..... Feb 54
Record-Changer Servicing (2 parts) ..... Sep 53, Jan 54
A Small, High-Quality Amplifier ..... Jul 53
Reflex Enclosure for 8" Speaker ..... May 53
Intercommunication Systems .... Mar 52
Crystal Phono Cartridges ..... Nov 51
Experiments in Audio ..... May 51

BUSINESS

TV Service Pricing Guide ..... Sep 60
Know the Law ..... Jun 60
Federal Tax Returns for Service Shop Owners ..... Mar 60
TV Repair the Customer Expects Feb 60
The Customer Is *Not* Always Right, But— ..... Jun 58
Solving the Guarantee Headache Apr 58
Your Wife Can Run Your Business ..... Feb 58
How Much Will It Cost to Fix It? ..... Oct 57
Getting Good Publicity Is Easy.. Aug 57
Bank Loans and How to Obtain Them ..... Jun 57
Repeat Business—Are You Getting Your Share? ..... Mar 57
Getting and Keeping Qualified Technical Personnel ..... Jan 57
Cost Accounting for the Service Shop ..... Nov 56
Give Estimates—Stop Aggravations ..... Sep 58
Walk-In Sales Items for the Service Shop ..... Jun 58
Window Displays ..... Jun 56
Shop Tickets ..... Jan 55
How Much Is Your Labor Worth? ..... Apr 54
Insurance Protection in the Service Field ..... Jan 52

CIRCUIT AND CHASSIS DESIGN, TV

Examining Motorized Tuner Mechanisms ..... Dec 60
Spotlighting the 1961 TV Lines.. Nov 60
Bench Servicing New Sets (3 parts) ..... Apr, Jun, Aug 59
Low-Voltage Power Supplies .... Jan 59
AGC Circuits for '58 (2 parts) ..... Apr, June 58
Now—Automatic Fine Tuning .. Feb 58
Keeping Up With Vertical Sweep.. Jan 58
Inside TV Tuners (part 5) ..... Dec 57
Circuit Popularity Guide ..... Dec 57
Inside TV Tuners (part 4) ..... Nov 57
Latest in Remote Tuning ..... Nov 57
Previews of 1958 TV Sets .... Nov 57
Inside TV Tuners (part 3) ..... Oct 57
Theory of Auxiliary Sync Circuits ..... Oct 57
Inside TV Tuners (part 2) ..... Sep 57
Inside TV Tuners (part 1) ..... Aug 57
TV Sets May Lose Another Stage ..... Jul 57
The Modern Vertical Sweep Circuit ..... Jul 57
Still More New Tubes ..... Mar 57
Remote Tuning Without Wires .. Mar 57
Hot-Chassis Safeguards ..... Mar 57
About These Automatic Tuning Devices ..... Feb 57
TV Sound From the 6DT6 ..... Dec 56
Operation of Damper Circuits ... Aug 56
Printed Wiring Boards ..... Aug 56
Video Amplifiers ..... Aug 56
Operation of Keyed AGC Systems Jul 56
Let's Take a Look at Some Components in Foreign-Made Radios ..... Jul 56
Voltage Dividers in B+ Circuits ..... May 56
The Horizontal Flyback System.. Apr 56
The Triode Phase Detector ..... Sep 55
Remote-Control Tuning Units for TV ..... Feb 55
Horizontal AFC Circuits (4 parts) ..... May, Jun, Aug, Sep 54
TV Sound IF Systems (3 parts) ..... May, Jun, Jul 54
Non-intercarrier TV Receivers ..... May 53
Use of UHF Converters ..... Mar 53
Vertical Sweep Systems ..... Jan 53
Design Trends in UHF Tuners and Converters ..... Jan 53
Circuits and Equipment for UHF Reception ..... Jan 53
Vibrator Power Supplies ..... Sep 52
Power Supplies ..... Jul 52
DC Restoration and Sync Separation (2 parts) ..... May, Jul 52
Vertical Retrace-Blanking Circuits ..... Sep 51
Video Detection and Amplification (2 parts) ..... Sep 51, Mar 52
Video IF Amplifiers ..... May 51
Keyed AGC Operation ..... Mar 51
Television Tuning Units (2 parts) ..... Jan, Mar 51

COLOR TV

Key to Quicker Color Servicing . . Feb 60
Isolating Color TV Troubles by Symptoms . . . . . Oct 59
Crosshatch Marks Chroma Phase Sep 59
Fine Points in Color-Sync Servicing . . . . . May 58
Basic Properties of the Color Signal . . . . . Sep 57
How a Rainbow Generator Sidelocks in Color Sync . . . . . Aug 57
Color Servicing Simplified . . . . . Jul 57
Letter to a Small-Town Technician . . . . . Jun 57
Alignment of Chrominance Bandpass Amplifiers . . . . . Jun 57
Here's Another New Color Receiver . . . . . May 57
Short Cuts in Color Servicing . . . . Feb 57
The Color Killer Circuit . . . . . Jan 57
What's Cooking in Color TV . . . Dec 56
Antennas and Their Relation to Color TV Reception . . . . . Nov 56
Looking Over the New Color Receivers . . . . . Nov 56
A New Development in Color Picture Tubes . . . . . Jan 56
High-Level Demodulation in Color Receivers . . . . . Dec 55
Color TV Training Series (16 parts) . . . . . May 54 to Sep 55
Questions and Answers About Color TV . . . . . Jul 55
A Glimpse Into Color Servicing (2 parts) . . . . . Feb, Apr 55
TV Colormath (5 parts) . . . . . May to Sep 54
Deflection Components for Color TV . . . . . Mar 54
Color TV and Your Test Equipment . . . . . Feb 54
Monochrome Reception by the Color Receiver . . . . . Jan 54
Color Decoding and Mixing . . . . Jan 54
Color Synchronization . . . . . Jan 54
The Color Picture Tube . . . . . Jan 54
Comparing Monochrome and Color Receivers . . . . . Jan 54
Compatible Color TV (2 parts) . . . . . Sep, Nov 53
A Comparison of CBS Color and Present Monochrome Standards Sep 51
The CBS Color TV System . . . . Jul 51

COMMUNICATIONS RADIO

Single-Sideband Adapters . . . . . Oct 60
Inside CB Radios . . . . . May 60
What About This New Citizens Band Service? . . . . . Feb 60
Aligning and Calibrating Communications Receivers . . . May 59
Getting Acquainted With Communications Receivers . . . Mar 59
Mobile Communications . . . . . Jan 59
Special Circuits in Communications Receivers . . . . . Nov 54

COMPONENTS, TOOLS, PRODUCTS

Hints on Making Control Replacements . . . . . Oct 60
Know Your Electronic Chemicals . . . . . Sep 60
Stretching CRT Life . . . . . Sep 60
Circuit Safety Devices . . . . . Apr 60
Batteries Today . . . . . Apr 60
Flyback-Transformer Replacement . . . . . Feb 60
Temperature-Compensating Capacitors . . . . . Dec 59
Questions and Answers on Deflection Yokes . . . . . May 59
Printed-Circuit Components . . . . Apr 59
The Silicon Power Rectifier Story . . . . . Mar 59
Check Those Electrolytics . . . . . Oct 58
Replacing Deflection Yokes . . . . May 58
Replacing Metal CRT's With Glass . . . . . May 58
Selection and Use of Hand Tools (part 2) . . . . . Mar 58
Wire and Its Uses . . . . . Feb 58
Selection and Use of Hand Tools (part 1) . . . . . Jan 58
Troubled by Color Codes? . . . . . Oct 57
Germanium Enters the B+ Rectifier Field . . . . . Sep 57
What's New in Batteries . . . . . Jul 57
Do Fuses Confuse You? . . . . . Jun 57
Flyback Replacement . . . . . May 57
Stock Guide for Popular Replacement Parts . . . . . May 57
Semiconductor Diodes . . . . . May 57
Special Resistors in TV Sets . . . . Feb 57
Replacing Twist-Prong Electrolytics . . . . . Feb 57
Aluminized Tubes . . . . . Jan 57
Silicon Rectifiers . . . . . Jan 57
Working With Soldering Guns . . Dec 56
Alignment Accessories . . . . . Nov 56
Selenium Rectifiers . . . . . Oct 56
New Styles in Capacitors . . . . . Sep 56
An 8" Check Tube . . . . . Jun 56
A New Development Towards Automation (Erie PAC modules . . . . . Apr 56
Chemical Aids to Servicing . . . . . Mar 56
Alignment Tools and Their Uses Mar 56
Carbide-Tipped Bits for Masonry Drilling . . . . . Dec 55
Extension Tip for Solder Gun . . Nov 55
Replacement Techniques for Controls . . . . . May 55
Checking Horizontal Output Transformers . . . . . Apr 55
Deflection Yokes . . . . . Mar 55
A TV-Receiver Check Tube . . . . Jan 55
Capacitors . . . . . Jan 55
Resistors . . . . . Oct 54
Traps for Standard Coil tuners . . Sep 54
Headsets for TV . . . . . Sep 54
Replacement Technique for Horizontal Output Transformers (2 parts) . . . . . Jul, Sep 53
Testing Selenium Rectifiers . . . . . Jul 53
Ailing Picture Tube? . . . . . May 53
Printed-Circuit Components . . . . Nov 52
Close-Tolerance Parts in TV Receivers . . . . . Jul 52
Radio and TV Fuse Replacement May 52
Electrostatic-Focus Picture Tubes . . . . . Jul 51
Ceramic Capacitors . . . . . Jul 51

MISCELLANEOUS

Report on TV Radiation Hazards . . . . . Dec 60
More Pleasure With Extra TV Speakers . . . . . Jan 60
A While-U-Wait Repair Bench . . . Jul 58
Individualized Service Pays Off . . . Jul 57
Building a TV Test Stand . . . . . Jun 57
Dressing Up Trade-Ins . . . . . Jan 57
Intercarrier Conversion . . . . . Nov 56
Deintermixture . . . . . Oct 56
Life on a UHF Island . . . . . Sep 56
Shelves and Cabinets for the Shop . . . . . Nov 55
From Split Sound to Intercarrier . . . . . Nov 54
Improving UHF Installations Through Cooperative Effort . . Mar 54
Service Shop on Wheels . . . . . Nov 53
UHF Operational Survey . . . . . Jul 53
UHF Report, Reading, Pa. . . . . May 53
Operation UHF . . . . . Mar 53
Converting the Olympic XL210 . . Sep 51
Keyed AGC Application (to 630 chassis) . . . . . May 51
Converting the RCA Victor 730TV-1 . . . . . May 51
High, Wide, and Handsome . . . . Mar 51

RADIO

Setting Up for Auto Radio Service . . . . . Aug 60
Radio and Hi-Fi Tube Guide . . . Aug 60
Expediting AC-DC Radio Repairs . . . . . Mar 60
Repairing Clock Radios . . . . . Jul 59
Build a Portable Unit for Radio Testing . . . . . Jun 59
What's New in Hybrid Auto Radios . . . . . Feb 59
Guide to Auto Battery Polarities . . . . . Mar 58
Tracking Superhets . . . . . Dec 57
Removing Radio from 1955 Chevrolet . . . . . Oct 57
FM for the TV Man . . . . . Aug 57
Planning for Auto Radio Service . . . . . May 57
Radio for the TV Man . . . . . Mar 57
AFC Circuits in FM Receivers . . . Jul 56
Hum Troubles in AC-DC Radios Jun 55
Radio Alignment . . . . . Mar 55
Auto Radio Servicing Can Be Profitable . . . . . Apr 54
It's Time for Portables . . . . . Apr 54
Servicing With a Scope (FM receiver) . . . . . Sep 53
Eliminating BC Interference Caused by TV Receivers . . . . . Nov 51

SERVICING TV

Regeneration in Picture-Signal Circuits . . . . . Dec 60
Secondary TV Waveform Checks . . . . . Nov 60
AC Outlet Voltages . . . . . Oct 60
Hints on Making Control Replacements . . . . . Oct 60
Causes and Cures for Negative Picture . . . . . Oct 60
Stretching CRT Life . . . . . Sep 60
Q & A on TV Alignment (2 parts) . . . . . Aug, Sep 60
A Key to Keyed AGC . . . . . Jun 60
That's the Way the Horizontal Sweeps . . . . . May 60
Have HV, No Raster . . . . . Apr 60
Tough-Dog Sync Troubles (3 parts) . . . . . Feb, Mar, Apr 60
Service Data Speeds Repairs . . . . Mar 60
Replacing Modular Component Sections . . . . . Jan 60
Mastering the PC Board . . . . . Jan 60
Rx for Interlace . . . . . Jan 60
Servicing TV Portables . . . . . Dec 59
Examining Video IF Response . . Nov 59
Why Test Tubes in the Home? . . Oct 59
Curing Brightness and Contrast Problems . . . . . Oct 59
Short-Lived TV Tubes . . . . . Sep 59
Let's Talk About Vertical Sweep Circuits (2 parts) . . . . . Aug, Sep 59
Scoping Modern TV Circuits (6BU8) . . . . . Aug 59
TV Tuner Alignment . . . . . Jul 59
Horizontal Sweep Circuits . . . . . Feb 59
Isolating Sync-Circuit Troubles . . Jan 59
Helpful Hints for PC Servicing . . Dec 58

IF Alignment Made Easy . . . . . Dec 58
Servicing Switch-Type Tuners . . Nov 58
Servicing Printed-Wiring Boards . . . . . Oct 58
Troubleshooting the Horizontal Multivibrator . . . . . Oct 58
Vertical Retrace-Line Elimination . . . . . Aug 58
Pulse-Width Horizontal AFC . . . . Jul 58
Analyzing the Vertical Circuit . . . Jun 58
Replacing Metal CRT's With Glass . . . . . May 58
Troubleshooting Sync-Separator Systems . . . . . Apr 58
Behind the IF Alignment Scene . . Apr 58
Using a Scope to Troubleshoot Sweep Circuits . . . . . Mar 58
Do-It-Yourselfers Are Soldering Now . . . . . Mar 58
Signal-Tracing RF and IF Circuits . . . . . Mar 58
A System for Starting on "Dogs" . . . . . Feb 58
Regeneration . . . . . Feb 58
Suffering From the Bends? . . . . . Jan 58
Troubleshooting With the Scope . . Jan 58
Dismantling a TV Tuner . . . . . Sep 57
Horizontal Output and High-Voltage Troubles . . . . . Sep 57
Let's Pull Less Chassis . . . . . Aug 57
TV Waveforms . . . . . Jul 57
Pinpointing Trouble in Vertical Sweep Systems . . . . . Jul 57
Adjacent and Co-Channel Interference . . . . . May 57
Working in the Cage . . . . . May 57
Tracing Through Wafer-Switch Circuits . . . . . Apr 57
Making CRT Setups . . . . . Apr 57
Horizontal AFC and Oscillator Troubles . . . . . Mar 57
More Than Just Tube Changing . . . . . Feb 57
Printed-Wiring Boards (part 5) . . Dec 56
Printed-Wiring Boards (part 4) . . Nov 56
Equipping the Service Case . . . . Nov 56
Voltage Measurements . . . . . Oct 56
Printed-Wiring Boards (part 3) . . Oct 56
New Alignment Techniques . . . . Sep 56
Cabinet Touch-Up . . . . . Sep 56
Printed-Wiring Boards (part 2) . . Sep 56
Printed-Wiring Boards (part 1) . . Aug 56
Troubles in Vertical Sweep Systems . . . . . Jun 56
Replacing Rivet-Mounted Components . . . . . Jun 56
Troubles in Sync Circuits . . . . . May 56
Troubles in AGC Circuits . . . . . Mar 56
Signal-Tracing in Sync Separators . . . . . Feb 56
Using a Solder Pot . . . . . Feb 56
Drilling Masonry . . . . . Jan 56
Replacing Components in Printed-Wiring Boards . . . . . Jan 56
Servicing Receivers of Unknown Origin . . . . . Dec 55
Troubles in Video Amplifiers, DC Restorers, and Picture Tubes . . Nov 55
Troubles in Video IF and Detector Systems (2 parts) . . . . . Sep, Oct 55
Servicing Modular TV Receivers (2 parts) . . . . . Aug, Oct 55
Troubles in TV Tuners . . . . . Jul 55
Removing the TV Chassis . . . . . Jun 55
Hints for TV Alignment . . . . . May 55
Vertical Nonlinearity and Foldover . . . . . Apr 55
Checking Horizontal Output Transformers . . . . . Apr 55
Applying the Finishing Touch . . . Apr 55
UHF Servicing . . . . . Nov 54
TV Picture Analysis . . . . . Mar 54
Checking Video Response . . . . . Jan 54
Cascode Tuner Installation . . . . . Jan 54
Causes and Cures for the Narrow Picture . . . . . Nov 53
Adjustment Procedure for UHF Strips . . . . . Sep 53
Replacement Technique for Horizontal Output Transformers (2 parts) . . . . . Jul, Sep 53
Testing Selenium Rectifiers . . . . . Jul 53
Servicing With the Scope . . . . . Jul 53
Ailing Picture Tube? . . . . . May 53
UHF Tuner Kit Field Installation Mar 53
UHF Strip Installation . . . . . Mar 53
The Value of Waveform Analysis (part 4) . . . . . Nov 52
Tube Troubles in TV Receivers Nov 52
A Guide to TV Model Identification (2 parts) . . . . . Sep, Nov 52
Signal Substitution in TV Servicing . . . . . Jul 52
Routine vs. Infrequent TV Troubles . . . . . Mar 52
The Value of Waveform Analysis (parts 1 to 3) . . . . Jan, Mar, May 52
Oscillations in TV Receivers . . . Nov 51
Checking Horizontal Output Transformers . . . . . Nov 51
Tracking Down TV-Receiver Intermittents . . . . . Jul 51

SPECIAL EQUIPMENT

Examining an Industrial Control Device . . . . . May 60
Radio Direction Finders for Boats . . . . . Apr 60
Large-Current Electron Tubes . . . Dec 59
Servicing Medical Amplifiers . . . . Oct 59
Servicing Electronic Organs . . . . . Jul 59
Room Air-Conditioner Maintenance (2 parts) . . . . . Apr, Jun 59
Servicing the Summer Air Conditioner . . . . . Aug 58
Small-Appliance Servicing . . . . . Aug 58
Installing Electronic Garage-Door Openers . . . . . Jul 58
Servicing Radiation Detectors . . . Oct 55
The Garage-Door Opener . . . . . Jan 55
Servicing Specialized Equipment (2 parts) . . . . . May, Jul 54
Autronic-Eye . . . . . Jul 53

TEST EQUIPMENT

Profit by Using a Field-Strength Meter . . . . . Nov 59
Special Uses for Your VOM and VTVM . . . . . Oct 59
Selecting the Proper Scope Probe . . . . . Sep 59
Making Use of Your Sweep Generator . . . . . Mar 59
Troubleshooting by Waveform Analysis (video-circuit response) . . . . . Dec 58
Probing for Trouble . . . . . Nov 58
How to Use a Scope . . . . . Oct 58
Using a Scope for Signal-Tracing . . . . . Apr 58
Using a Scope to Troubleshoot Sweep Circuits . . . . . Mar 58
Scope-Waveform Calibration . . . Dec 57
Know Your VTVM . . . . . Apr 57
Choosing a Scope . . . . . Dec 56
Oscilloscope Maintenance . . . . . Nov 56
Know Your Oscilloscope (6 parts) . . Nov 55; Jan, Feb, May, Jun, Jul 56
Some Case Histories of Test-Equipment Troubles . . . . . Nov 55
Diagrams for Setting Up Test Equipment . . . . . Sep 55
Test-Instrument Coupling Methods . . . . . Feb 54
Intermittent Recorder . . . . . Feb 54
Color TV and Your Test Equipment . . . . . Feb 54
Test Probes . . . . . Nov 53
UHF and Your Test Equipment Jan 53
Parts Lists for Impedance-Measuring and Null-Indicating Devices . . Sep 51
Oscilloscope Modification for 120-Cycle Synchronization . . . . . Sep 51
An Impedance-Measuring Device Jul 51

THEORY

All We Want Are the Facts . . . . Jun 60
Class A Amplifiers . . . . . Nov 59
Reading Between the Lines . . . . . Oct 59
Understanding the Decibel . . . . . Aug 59
Horizontal Sweep Circuits . . . . . Feb 59
The FM Signal . . . . . Jul 58
Resonant Circuits (3 parts) . . . . . Feb, Apr, Mar 57
Analyzing Lissajous Patterns . . . . Oct 56
Operation of Damper Circuits . . Aug 56
Time Constants . . . . . Mar 56
Voltage Phases in Transformers . . Jan 56
Polar Graphs . . . . . Dec 55
Power Factor . . . . . Nov 55
Vectors . . . . . Dec 54
TV Colormath (5 parts) May to Sep 54
Antenna Principles . . . . . Apr 54
Analyzing Horizontal Deflection Waveforms . . . . . Mar 54
Color Within 6 Megacycles . . . . Mar 54
Microvolts Per Meter . . . . . Feb 54
Mathematics—A Servicing Tool . . . . . Feb 54
Glossary of UHF Television Terms . . . . . Jan 53
The Decibel . . . . . Mar 52

TRANSISTORS AND APPLICATIONS

Fundamental Transistor Theory . . . . . Nov 60
Voltage Analysis of Transistor Circuits . . . . . Aug 60
P's and Q's of Transistors . . . . . Jul 59
Transistors With Power . . . . . Feb 59
Advanced Troubleshooting Techniques for Transistor Radios . . . . . Aug 58
Pocket-Sized Portables . . . . . Jul 58
More Facts on Servicing Transistor Radios . . . . . Oct 57
Transistor Application Chart No. 2 . . . . . Jul 57
Troubleshooting and Signal-Tracing in Transistor Radios . . . . . Jun 57
Working with Transistor Radios . . Mar 57
Transistor Application Chart No. 1 . . . . . Jan 57
Servicing the Transistor Radio . . Mar 55
Transistor Radios are Here . . . . Jan 55
The Transistor Story (3 parts) . . . . . Sep 53; Feb, Mar 54
Glossary of transistor terms . . . . Sep 53

TUBES

Facts About Tube Substitution . . Oct 60
Large-Current Electron Tubes . . Dec 59
Why Test Tubes in the Home? . . Oct 59
Short-Lived TV Tubes . . . . . Sep 59
Keeping Posted on TV Tubes . . . Jun 59
Guide to European Tubes . . . . . Sep 58
A Gallery of Triode-Pentodes . . . . . Jun 57
Changes in Tube Design . . . . . Apr 56
Grid Emission and Gas . . . . . Aug 55
Checking Filaments in a Series String . . . . . May 55
New Tubes . . . . . Oct 54
New Tubes for Series Strings . . . Sep 54
Understanding Receiving-Tube Operation . . . . . Apr 54
UHF Tubes . . . . . Jan 53